

White Paper Document No. MWA-017-EN_05_1312 December 2013

NCGuide Academic packages

Authentic FANUC CNC software on a PC for the most effective learning environment



1 Int	troduction	5								
1.1	NCGuide Academic packages6									
1.2	FANUC CNCs supported6									
2 A c	ademic Applications	7								
2.1	Instructor demonstration	7								
2.2	Classroom exercises	7								
2.3	Students homework	8								
2.4	Flipping the classroom	8								
2.5	Distance learning	8								
2.6	CAD/CAM integration	8								
2.7	Operation training	8								
2.8	Part programming training	9								
2.9	CNC Certification Cart	9								
3 S u	ipporting the CNC workflow	10								
3.1	Creating part programs	10								
3.2	Loading part programs	10								
3.3	Tool setup	11								
3.4	4 Graphical part program verification11									
3.5	Editing part programs	12								
3.6	Work offsets	12								
3.7	Run program	12								
3.8	Tool wear offsets	12								
4 C N	ICs, displays, MDI panels and options	13								
4.1	FANUC CNC models supported	13								
4.2	FANUC CNC displays supported	13								
	4.2.1 Changing the CNC display	14								
	4.2.2 Changing the display mode									
4.3	4.3.1 Changing the MDI key panel	14 14								
4.4	Examples of CNC display and MDI panel combinations									
	4.4.1 Series 0 <i>i</i> -D lathe, 8.4" display, picture mode									
	4.4.2 Series 0 <i>i</i> -D mill, 10.4" display, picture mode									
	4.4.3 Series 31 <i>i</i> MODEL B mill, 10.4" display, picture mode	17								
15	List of ontions	10 10								
۲.5 ۵ ۵	List of options									
4.0		20 ວະ								
4.7										

Ор	peration	30
5.1	Starting NCGuide	
5.2	Components 5.2.1 0 <i>i</i> -D components 5.2.2 30 <i>i</i> . 31 <i>i</i> and 35 <i>i</i> components	31
53	CNC Mode selection	33
5.5	5.3.1 FDIT - Program editing mode	
	5.3.2 MEM – Memory operation	
	5.3.3 MDI operation mode	
5.4	MDI key operation	
	5.4.1 MDI keys	
5.5	Soft key operation	
5.6	Mini operator panel operation	
5.7	Screens display	
	5.7.1 Position screen	
	5.7.2 Program screen	
	5.7.3 Setting screen	
	5.7.4 Parameter screen	
	5.7.5 Message screen	
	5.7.6 Graphic screen	
5.8	Editing part programs	
	5.8.2 Altering a word	47. 47
	5.8.3 Inserting a word	48
	5.8.4 Deleting a word	
5.9	Selecting part programs	
	5.9.1 Selection using program call operation	
	5.9.2 Selection using the part program list	
5.10	0 Deleting part programs	
	5.10.1 Deletion using program call operation	
	5.10.2 Deletion using the part program list	
5.11	1 Part program execution	
	5.11.1 Part program execution	
	5.11.2 Program graphic function check	
_	5.11.3 Single block execution	
5.12	2 Multi-language display	
	5.12.1 Language switch procedure	51
5.13	3 Exiting NCGuide	51

6	ΜA	NUAL	L GUIDE i	52					
	6.1	What is MANUAL GUIDE <i>i</i>							
	6.2	Academ	nic applications of MANUAL GUIDE <i>i</i>	52					
	6.3	Main Fe	eatures of MANUAL GUIDE <i>i</i>	53					
	6.4	Navigat 6.4.1	tion to MANUAL GUIDE <i>i</i>	54 54					
		6.4.2	MANUAL GUIDE <i>i</i> screen components	55					
	6.5	Overvie	ew of creating a MANUAL GUIDE <i>i</i> part program						
	6.6	Notes o	on creating part programs	57					
		6.6.1	Commands required before machining cycle input	57					
		6.6.2	Machining cycles	58					
7	Мa	chine	e compositions	59					
	7.1	Machine	e Composition setting tool	59					
	7.2	Option	Setting	60					
	7.3	Parame	ters	60					
8	NC	Guide	e Academic packages	61					
	8.1	System	requirements	61					
	8.2	Differen	nces from the CNC in operation	62					
9	Su	mmar	У	62					

1 Introduction

NCGuide Academic packages are FANUC CNC software running on a PC, providing a 100% authentic operation and part programming environment at a fraction of the cost of using a hardware simulator or a production machine tool. Comprehension and retention is enhanced as students perform repetitive hands-on exercises in an ergonomically friendly environment.

Students can practice common procedures and experiment safely with minimum supervision and without risks to people, tooling or machines.

NCGuide Academic packages provide access to the latest CNC technology and support multiple control configurations for both turning and milling.

NCGuide Academic packages improves the effectiveness of CNC instruction through:

- Instructor demonstrations in the classroom and online for distance learning
- Classroom exercises that provide a superior hands on experience with minimum supervision
- Homework that can be completed anytime and anywhere
- Distance learning that is supported through both online instructor demonstrations or to complement online video instruction, and independent student exercises
- Enhanced CAD/CAM generated part program testing
- Comprehensive operation and part programming support, including Custom Macro programming

NCGuide Academic packages support the complete CNC programming, setup operation and part program execution workflow:

- Create part programs on the CNC with conventional G-code editors or using the MANUAL GUIDE *i* conversational programming
- Upload part programs created externally with text editors or CAD/CAM systems
- Complete tool setup for tool geometry
- Verify the part program using 3D solid model animation or tool path plotting visualizations and using the part program check screen
- Part programs can be modified using the G-code editor
- Work offsets can be established
- Part programs can be executed at the programmed feed rate, or in accelerated simulation rates
- Tool offsets can be adjusted

1.1 NCGuide Academic packages

NCGuide Academic package for Classroom provides network licensing. Up to 16 concurrent students can use the simulation software at the same time, from a larger pool of potential users. Each individual student can use any of the controls and configurations supported. As long as students can access the network within the campus or via the Internet they can run the simulator on any PC that has the software installed. This provides flexibility for students and staff for practical exercises, homework and distance learning.

NCGuide Academic package for Homework is value priced for an individual student, or for an instructor to test drive the software before committing to the Classroom package. The software is identical to the classroom package, except the licensing is provided with a plug-in USB key that is only valid for one year. The price of the package makes it suitable for including in a year-long certificate program.

1.2 FANUC CNCs supported

The current versions of NCGuide Academic packages support:

- FANUC Series 0i-D (0i-TD and 0i-MD)
- FANUC Series 31i-B
- FANUC Series 30i-B
- FANUC Series 31i-A
- FANUC Series 31i-LB (laser cutting CNC)
- FANUC Series 31i-PB (punch press CNC)
- FANUC Series 35i-B

2 Academic Applications

2.1 Instructor demonstration

NCGuide Academic packages can be projected to a large classroom display just like any other PC-based program, providing an effective visual aid for demonstrating concepts and examples during lectures.

The instructor can share his screen to remote students using suitable software for instructor-led distance learning applications. Student may also be able to control the presenting computer for interactive exercises.

All aspects of CNC operation and part programming can be demonstrated including:

- Milling and turning applications
- Creating a part programming on the CNC
- · Loading a program into the control from an external source
- Tool geometry setup and adjustment
- Graphical part program verification for syntax and sequence of operation errors
- Part program editing
- Work offset setting and adjustment
- Part program execution
- Adjusting tool wear offsets

2.2 Classroom exercises

Students can perform operation and programming exercises in the classroom. This is especially useful if, as is typical, there are insufficient machines for all the students to use at the same time. The instructor can focus on monitoring students using machine tools to ensure safe operation, while the remaining students can use NCGuide to pre-test part programs or to learn additional concepts.

The instructor can provide a specific machine composition for the exercise, with the CNC type, options, parameter



settings, existing part programs and subprograms, tool and work offsets all preselected.



2.3 Students homework

Students that can access the schools network remotely can also run NCGuide. The software is loaded on the student's computer and only the licensing is controlled via the network. This means the student gets the performance benefits of a local application and the network is not loaded with large data transfers.

An instructor can provide a customized machine composition for exercises, with the CNC type,



options, parameter settings, existing part programs and subprograms, tool and work offsets all preconfigured. Problems can be designed for the student to solve.

2.4 Flipping the classroom

NCGuide Academic packages are ideal when lectures and standard exercises are performed with minimal supervision, reserving the primary instructor interactions for in-class homework assignments.

2.5 Distance learning

NCGuide is an effective distance learning tool that allows the user to perform comprehensive exercises in CNC operation and programming, complimenting existing distant learning systems. Licensing is controlled via the network so the student gets the performance benefits of a local application and the network is not taxed with large data transfers. An instructor can also demonstrate the application across the web for instructor-led distance learning applications.

2.6 CAD/CAM integration

NCGuide a valuable tool in CAD/CAM class. The first execution of the part program after completing the CAM post processing can be performed on NCGuide. Conventional tool path plotting graphics or the 3D solid model animation can be used to check syntax and tool paths in a safe, low-cost environment.

2.7 Operation training

NCGuide is ideal for operational training. All standard CNC operational screens can be selected and all standard procedures can be practiced. You can:

- create and edit part programs
- search for words and safe start blocks
- upload and download part programs
- test for syntax and tool path geometry errors
- edit and visualize workpiece coordinate offsets
- edit and visualize tool geometry and tool wear offsets

Users can expand their knowledge by learning the features available with newer controls - even if the control is not available in the workshop. Academic students can get hands on experience with the latest controls to enhance their value to hiring companies, and workers already in industry can build experience prior to new machine purchases.

For the most realistic and effective learning environment, users can setup machine compositions to emulate a particular machine's CNC.

2.8 Part programming training

NCGuide supports both conventional G-code part programming and the easy-to-use, yet powerful MANUAL GUIDE *i* conversational part programming. You can:

- create and edit machining center, lathe and compound machining part programs
- visualize conventional part programs with tool path simulation
- visualize part programs with 3D solid model animation or tool path plotting
- generate cycle time estimates
- create and test Custom Macro subroutines
- visualize the effect of workpiece and tool offsets
- visualize the details of canned cycles and advanced interpolation modes
- test CAD/CAM programs prior to sending to a machine

Manual Guide *i* conversational part programs can be developed on the simulator and then converted to conventional G-code to run on any FANUC CNC.

2.9 CNC Certification Cart

NCGuide can be used with the Levil CNC Certification Cart to bring complete programming and setup instruction into the classroom. Students can create, test and debug part programs using NCGuide, save the program to a USB memory port or network drive directory and then load the programs into the CNC Certification Cart. All setup including tool geometry and workpiece

coordinate system offsets can be set and a part produced. By allowing the complete programming and setup process to be experienced in the classroom means that students are more efficient and effective when using workshop machines.

Schools without workshop resources can use NCGuide and the CNC Certification Cart to provide an effective introduction to CNC machining, preparing them for future courses at college.



3 Supporting the CNC workflow

3.1 Creating part programs

Part programs can be created on the CNCs using the standard G-code editors or using MANUAL GUIDE *i* conversational programming.

The FANUC traditional G-code word editor and the more contemporary character editor are supported.

MANUAL GUIDE *i* conversational programming simplifies the generation of a part programming and focuses the student on the sequence of operations required rather than on the detailed G-code.

MANUAL GUIDE *i* also provides fixed sentence programming to generate multiple lines of G-code with just a few keystrokes. Fixed sentences can be established for sequence of operations such as program starting blocks, tool change blocks, material feeds and speeds and part program end blocks.



NCGuide Academic packages support a wide range of G-codes from the basic through to advanced concepts including Custom Macros.

3.2 Loading part programs

Part programs can be created externally using a PC-based editor or by a CAD/CAM post-processor and input into the control using standard CNC screens.

Part programs are loaded using the memory card interface. The virtual memory card may be located on a USB memory stick for student convenience, or on any directory on the PC or a network drive.

Instructors can provide sample part programs to be uploaded into the CNC. The part programs can include syntax or sequence of operations errors, for the student to test and debug.

3.3 Tool setup

Setting the tool geometry data accurately is a critical step in machine setup. The correct tools must be loaded into the correct tools stations to correspond with the part program assignments (or the part program must be edited).

For milling machines the correct tool length and diameter must be entered into the tool offset tables. NCGuide supports Tool Offset Memory C, displaying tool data and tool wear offsets for length and diameter in separate column, eliminating the need for error prone math calculations. Legacy tool offset systems are also supported.

For turning machines, the correct tool geometry data for X and Z must be entered along with the appropriate tool nose radius and tip offset.



When using MANUAL GUIDE *i*, additional data is required to describe the type and set of the tool to support the solid model machining simulation.

3.4 Graphical part program verification

Before executing a part program with the material in place, it is usual to check it for syntax problems and ensure the correct order of operations.

Verification is best achieved using the graphics display. Both the standard GRAPH display and the MANUAL GUIDE *i* solid model animation are supported in NCGuide Academic packages.

Solid model animation is superior for several reasons:

- Easier to visualize tooling and machining operations
- Simulation is performed without moving axes
- 3D tool path plotting is also selectable

Conventional part programs can be simulated using the 3D solid model animation. A block must be added

at the beginning of the part program to describe the material blank, the tool types must be defined in the tool data table, and a D-code must be specified at each tool change.



Advanced screens available with the FANUC Series 31i-MODEL B control simplify the testing and debugging of Custom Macro programs by displaying both the macro statements and the result values simultaneously.

3.5 Editing part programs

Part programs can be edited on the CNC using the standard part program editors or in the MANUAL GUIDE *i* environment. Students can practice all editing operations from the simple alter or delete commands through to advanced search and replace commands.

3.6 Work offsets

Work offsets can be set to shift the working coordinate system to the part program zero point.

For machining centers, G54 through G59 and G54 P1 through G54 P48 are available.

For turning, G54 through G59 and the external work shift is available.

3.7 Run program

The part program can be executed at the programmed feed rate. The program check screen displays the part

program and the active positions and model G-codes simultaneously.

3.8 Tool wear offsets

Though NCGuide cannot simulate actual tool wear, the tool wear offset tables can be updated and their effect on axis positions can be demonstrated.



4 CNCs, displays, MDI panels and options

NCGuide Academic packages support a wide range of FANUC CNC models, displays and MDI panels.

4.1 FANUC CNC models supported

NCGuide Academic packages support the following FANUC CNC models:

- FANUC Series 0*i* MODEL D (lathe and mill)
- FANUC Series 31*i* MODEL A (lathe and mill)
- FANUC Series 31*i* MODEL B (lathe, mill, laser and punching)
- FANUC Series 30*i* MODEL B (lathe and mill up to 10 axes)
- FANUC Series 35*i* MODEL B

Multiple machine compositions can be created for each model with the following maximum machine configuration:

Maximum controlled axes	4 axes
Maximum controlled paths	1 path
Maximum part program storage size	32 KB
Maximum number of registered part programs	64

4.2 FANUC CNC displays supported

NCGuide Academic packages support the following FANUC displays:

Display	Models	Optimum PC Screen Resolution
8.4"	All	1280 x 1200
10.4"	All	1280 x 1200
15"	Series 30i/31i MODEL A/B	2048 x 1536

If NCGuide does not fit the screen in picture mode due to a low display resolution, scroll bars are displayed. Alternatively, NCGuide can use Window mode to display the CNC screen, MDI panel and mini operator's panels in separate windows. The PC keyboard can be used for most MDI inputs. Window mode and PC keyboard input may be preferred for laptop computers.

4.2.1 Changing the CNC display

The display size can be changed quickly by selecting from the choices listed on the Display Size menu or by using the Setting Management tool. In Picture Mode, the Display Size menu is displayed by right-clicking on the CNC control. In Window Mode, the Display Size menu is accessible from the View menu. After changing the display size, you must exit and restart NCGuide to activate the new screen size.

4.2.2 Changing the display mode

The display mode can be changed quickly by selecting Window Mode or Picture Mode on the Display Mode menu or by using the Setting Management tool. In Picture mode, the Display Mode menu is displayed by right-clicking on the CNC control. In Window mode, the Display Mode menu is accessible from the View menu. After changing the display mode, you must exit and restart NCGuide to activate the new screen mode.

4.3 FANUC MDI key panels supported

NCGuide Academic packages support the following FANUC MDI key panels:

MDI Panel	Models
ONG 'T'	All
ONG 'M'	All
QWERTY	Series 30i/31i MODEL A/B

4.3.1 Changing the MDI key panel

The MDI key panel can be changed quickly by selecting from the choices listed on the Display Size menu or by using the Setting Management tool. In Picture Mode, the MDI Key menu is displayed by right-clicking on the CNC control. In Window Mode, the MDI menu is accessible from the View menu. Note that in Window mode you can chose not to display an MDI key panel if you intend to provide all input though the PC keyboard. After changing the MDI key, the new MDI key panel is displayed.

4.4 Examples of CNC display and MDI panel combinations

4.4.1 Series 0*i*-D lathe, 8.4" display, picture mode

		ABSO		eries E PO	oi-d SITI	ION 00001 N00000 0 • 0 0 0 0 • 0 0 0							
		RUN ACT. A)	TIM F	E :** *	0 0M <** >	H 4M M/MI ***	PAR ICYC NSA	CTS (CLE 1 CT 9:37	COUNT FIME	Г ОН О Т О О Т О	0M /MIN 000	5 0S	
ſ	RESET		ADS		REL				DEE			•	
	0 _P	N _Q	G _R	7 _A	8 † B	9 _D	ALTER	CAN	POS	PROG	SET •		
	\mathbf{x}_{c}	Ζ _γ	FL	4 <mark>↓</mark>	5 🖔	6 → _{SP}			SYSTEM	? MESSAGE	GRAPH		
	M_1	s _κ	T _J	1	2 ‡	3 _	DELETE			t,		1 PAGE	
	U _H	W_v	^{ЕОВ} Е	-+	0 *	• ,	① SHIFT			Ŧ	-	PAGE	
l	0			EDIT		ET SYSRE	CYCLE STOP		SPE	CIAL			J

0i-D CNC, 8.4" display, ONG 'T' MDI panel in lathe mode

0	FANUC Series 0i-	MODEL D			0
				1100000	
	ABS	1.UTE		NOODOO	
	X	0.000	X 0.000 Y 0.000	X 0.000 Y 0.000	
	Y	0.000	Z 0.000	Z 0.000	
	Z	0.000			
	MOI		-		
	G17 G80 G69 H G90 G98 G15 D		5		
	622 650 640.1 694 667 625 <mark>S</mark>	T RI	UN TIME ØH 5M	CYCLE TIME OH OM OS	
	621 697 6160 640 654 613.1				
		B	>_	S 0 T0000	
				09:33:46	
			TE VE		
0				PANUG	0
0			$G^{\circ}P \bullet^7$	8 ,9 📀	U
	EDIT			5 6 3	
		XY			
MDI	PATR	HELP I J	KR 1	2 3	
CYCLE	CYCLE	[*] M [⊺] S [*]	T [⁺] L −	0 ·	
SINGLE		Ê D *	H ^{sp} B /	ов 🥢 文	
BLOCK	SKIP			INPUT	
		PAGE	t Pos F		
O		SPECIAL PAGE	•		
0	00		arateri fit		0

4.4.2 Series 0*i*-D mill, 10.4" display, picture mode

0i-D CNC, 10.4" display, ONG 'M' MDI panel in machining mode

FANUC Series 311-MODEL B
ACTUAL POSITION 00001 N00000
$\begin{array}{ c c c c c c c c c c c c c c c c c c c$
MODAL F Øннимін G00 680 615 F M G17 698 640.1H S Øинимін G22 667 6160 T T
694 697 613.15 40 621 654 650.1 RUN TIME 0H52H455 640 664 654.2 B CYCLE TIME 0H 0M 0S 649 669 680.5 A>_ MEM ***** **** 09:38:58 ABSOLU RELATI 61.1
AUTO EDIT BESET HELP POS PROG STO GRAPH CUSTOM CUST
$ \begin{array}{cccccccccccccccccccccccccccccccccccc$
ABC Z X C V B N M EOB I 1 2 3
CTRL AUX PAGE + + + AUX

4.4.3 Series 31*i* MODEL B mill, 10.4" display, picture mode

31i MODEL B CNC, 10.4" display, QWERTY MDI panel in machining mode

4.4.4 Series 0*i*-D mill, 10.4" display, window mode

FANUC NCGuide/NCGuidePro	P L C	the second second	
<u>File View Window H</u> elp			
ACTUAL POSITION		00001	NAAAAA
ABSOLUTI	E		
X	0.000	X 0.000 Y 0.000	X 0.000 Y 0.000
ΙΫ́	0.000	Z 0.000	Z 0.000
	0.000		
HODOL		F	Ø
GØØ G49 G64 F	м	<u> </u>	
G90 G98 G15 D G22 G50 G40 1	т	5	PARTS COUNT 8
G94 G67 G25 S G21 G97 G160		RUN TIME OH 5M	CYCLE TIME OH OM OS
640 654 613.1			
		A>_	S 0 T0000
	1 1 1		10:54:38
		TE VE	
MDI) E 0		
RESET O	´N [≞] G Ĕf	⊃ <mark>~</mark> 7 ₁ 8	9 ALTER
UN	V V V ?c	1 5	6
X	ΥΖC	x <u>+</u> 4 ∿2	
<u>, і</u> і	^A J [®] K [−] F	1,2	,3 🖉
ncu ² 4	- X -		UELETE
"M	STI	0	·
Û C	¹ SP		1/ €
SHIFT F	UHE	5 / 205	CAN INPUT
<u>†</u>			
PAGE	+ -	POS PROG S	ET CUSTOM1
SPECIAL PAGE	+		
		SYSTEM MESSAGE	GRAPH CUSTOM2

0i MODEL D CNC, window mode

4.5 List of options

	0i-MOI	DEL D	31i-MOE	DEL A/B
Feature Description	Machining	Lathe	Machining	Lathe
INCH/METRIC SELECTION	•	٠	•	•
SEQUENCE NUMBER COMPARISION & STOP	•	•	•	•
INCREMENTAL SYSTEM C	•	•	•	•
STORED STROKE LIMIT 2ND/3RD	•	•	•	٠
PRE-TRAVEL STROKE LIMIT CHECK	•	•	•	•
CHUCK/TAILSTOCK BARRIER		•		•
PROGRAM RESTART	•	•	•	•
EXPONENTIAL FUNCTION INTERPOLATION			•	•
POLAR COORDINATE INTERPOLATION		•	•	•
	•	•	•	•
	•		•	•
			•	•
			•	•
F1-DIGIT FFFD	•		•	-
	•		•	
	•		•	
	•		•	
SINGLE DIRECTION POSITIONING	•		•	
3RD/4TH REFERENCE RETURN	•	•	•	•
WORKPIECE COORDINATE SYSTEM	•	•	•	•
WORKPIECE COORDINATE SYSTEM PRESET	•	•	•	•
ADDITION OF WORKPIECE COORDINATE SYSTEM 48-PAIRS	•	-	•	•
DIRECT DRAWING DIMENSION	-	•	-	•
G CODE SYSTEM B/C		•		•
		•		•
OPTIONAL ANGLE CHAMEERING/CORNER R	•	-	•	-
	•	•	•	•
ADDITIONAL COMMON MACRO VARIABLES	•	•	•	•
PATTERN DATA INPUT	•	•	•	•
MULTIPLE REPETITIVE CYCLES		•	-	•
MULTIPLE REPETITIVE CYCLES II		•		•
CANNED CYCLES FOR DRILLING	•	•	•	•
SCALING	•		•	•
AUTOMATIC CORNER OVERRIDE	•		•	
COORDINATE SYSTEM ROTATION	•		•	•
PROGRAMMABLE MIRROR IMMAGE	•		•	•
FIGURE COPY			•	
2ND AUXILIARY FUNCTION	•	•	•	•
TOOL OFFSET MEMORY 400 PAIRS	•		•	
TOOL OFFSET MEMORY C	•		•	
Y AXIS OFFSET		•		•
TOOL OFFSET	•		•	
TOOL RADIUS/TOOL NOSE RADIUS COMPENSATION	•	•	•	•
TOOL GEOMETRY/WEAR OFFSET		•		•
TOOL LIFE MANAGEMENT	•	•	•	•
BACKGROUND EDITING	•	٠	•	•
MACHINE TIME STAMP			•	•
RUN HOUR AND PARTS COUNT	•	٠	•	•
GRAPHIC DISPLAY	•	٠	•	•
BACKGROUND EDITIING	•	٠	•	•
MANUAL GUIDE I	•	•	•	•

4.6 Lathe G-codes

G code system		Group	Function	
Α	В	С	Group	FUNCTION
G00	G00	G00		Positioning (Rapid traverse)
G01	G01	G01		Linear interpolation (Cutting feed)
G02	G02	G02		Circular interpolation CW or helical interpolation CW
G03	G03	G03		Circular interpolation CCW or helical interpolation CCW
G02.2	G02.2	G02.2	01	Involute interpolation CW
G02.3	G02.3	G02.3	01	Exponential interpolation CW
G02.4	G02.4	G02.4		3-dimensional coordinate system conversion CW
G03.2	G03.2	G03.2		Involute interpolation CCW
G03.3	G03.3	G03.3		Exponential interpolation CCW
G03.4	G03.4	G03.4		3-dimensional coordinate system conversion CCW
G04	G04	G04		Dwell
				Al contour control (command compatible with high precision
G05	G05	G05	00	contour control), High-speed cycle machining, High-speed
			00	binary program operation
G05.1	G05.1	G05.1		AI contour control / Nano smoothing / Smooth interpolation
G05.4	G05.4	G05.4		HRV3, 4 on/off
G06.2	G06.2	G06.2	01	NURBS interpolation
G07	G07	G07		Hypothetical axis interpolation
G07.1	G07.1	G07.1		Cylindrical interpolation
(G107)	(G107)	(G107)		
G08	G08	G08		Advanced preview control
G09	G09	G09	00	Exact stop
G10	G10	G10		Programmable data input
G10.6	G10.6	G10.6		Tool retract and recover
G10.9	G10.9	G10.9		Programmable switching of diameter/radius specification
G11	G11	G11		Programmable data input mode cancel
G12.1	G12.1	G12.1		Polar coordinate interpolation mode
(G112)	(G112)	(G112)	21	
G13.1	G13.1	G13.1	21	Polar coordinate interpolation cancel mode
(G113)	(G113)	(G113)		
G17	G17	G17		XpYp plane selection
G18	G18	G18	16	ZpXp plane selection
G19	G19	G19		YpZp plane selection
G20	G20	G70	06	Input in inch
G21	G21	G71	00	Input in mm
G22	G22	G22	09	Stored stroke check function on
G23	G23	G23	00	Stored stroke check function off
G25	G25	G25	08	Spindle speed fluctuation detection off
G26	G26	G26	00	Spindle speed fluctuation detection on

G code system			Function		
Α	B	С	Group	Function	
G27	G27	G27		Reference position return check	
G28	G28	G28		Return to reference position	
G28.2	G28.2	G28.2		In-position check disable reference position return	
G29	G29	G29		Movement from reference position	
G30	G30	G30	00	2nd, 3rd and 4th reference position return	
G30.2	G30.2	G30.2		In-position check disable 2nd, 3rd, or 4th reference position return	
G31	G31	G31		Skip function	
G31.8	G31.8	G31.		EGB-axis skip	
G32	G33	G33		Threading	
G34	G34	G34		Variable lead threading	
G35	G35	G35		Circular threading CW	
G36	G36	G36		Circular threading CCW (When bit 3 (G36) of parameter No. 3405 is set to 1) or Automatic tool offset (X axis) (When bit 3 (G36) of parameter No. 3405 is set to 0)	
G37	G37	G37	01	Automatic tool offset (Z axis) (When bit 3 (G36) of parameter No. 3405 is set to 0)	
G37.1	G37.1	G37.1		Automatic tool offset (X axis) (When bit 3 (G36) of parameter No. 3405 is set to 1)	
G37.2	G37.2	G37.2		Automatic tool offset (Z axis) (When bit 3 (G36) of parameter No. 3405 is set to 1)	
G38	G38	G38		Tool radius/tool nose radius compensation: with vector held	
G39	G39	G39		Tool radius/tool nose radius compensation: corner rounding interpolation	
G40	G40	G40		Tool radius/tool nose radius compensation : cancel	
G41	G41	G41		Tool radius/tool nose radius compensation : left	
G42	G42	G42		Tool radius/tool nose radius compensation : right	
G41.2	G41.2	G41.2		3-dimensional cutter compensation : left (type 1)	
G41.3	G41.3	G41.3		3-dimensional cutter compensation :(leading edge offset)	
G41.4	G41.4	G41.4		3-dimensional cutter compensation : left (type 1) (FS16i-compatible command)	
G41.5	G41.5	G41.5	07	3-dimensional cutter compensation : left (type 1) (FS16i-compatible command)	
G41.6	G41.6	G41.6		3-dimensional cutter compensation : left (type 2)	
G42.2	G42.2	G42.2		3-dimensional cutter compensation : right (type 1)	
G42.4	G42.4	G42.4		3-dimensional cutter compensation : right (type 1) (FS16i-compatible command)	
G42.5	G42.5	G42.5		3-dimensional cutter compensation : right (type 1) (FS16i-compatible command)	
G42.6	G42.6	G42.6	1	3-dimensional cutter compensation : right (type 2	
G40.1	G40.1	G40.1		Normal direction control cancel mode	
G41.1	G41.1	G41.1	19	Normal direction control left on	
G42 .1	G42 .1	G42 .1		Normal direction control right on	

G	G code system		0.000	Function	
А	В	С	Group	Function	
G43	G43	G43		Tool length compensation + (Bit 3 (TCT) of parameter No. 5040 must be "1".)	
G44	G44	G44		Tool length compensation - (Bit 3 (TCT) of parameter No. 5040 must be "1".)	
G43.1	G43.1	G43.1		Tool length compensation in tool axis direction (Bit 3 (TCT) of parameter No. 5040 must be "1".)	
G43.4	G43.4	G43.4	23	Tool center point control (type 1) (Bit 3 (TCT) of parameter No. 5040 must be "1".)	
G43.5	G43.5	G43.5		Tool center point control (type 2) (Bit 3 (TCT) of parameter No. 5040 must be "1".)	
G43.7 (G44.7)	G43.7 (G44.7)	G43.7 (G44.7)		Tool offset (Bit 3 (TCT) of parameter No. 5040 must be "1".)	
G49 (G49.1)	G49 (G49.1)	G49 (G49.1)		Tool length compensation cancel (Bit 3 (TCT) of parameter No. 5040 must be "1".)	
G50	G92	G92	00	Coordinate system setting or max spindle speed clamp	
G50.3	G92.1	G92.1	00	Workpiece coordinate system preset	
-	G50	G50	18	Scaling cancel	
-	G51	G51	10	Scaling	
G50.1	G50.1	G50.1	22	Programmable mirror image cancel	
G51.1	G51.1	G51.1		Programmable mirror image	
G50.2	G50.2	G50.2		Polygon turning cancel	
(G250)	(G250)	(G250)	20	Polygon turning	
G51.2	G51.2	G51.2	20		
(G251)	(G251)	(G251)			
G50.4	G50.4	G50.4		Cancel synchronous control	
G50.5	G50.5	G50.5			
G50.6	G50.6	G50.6			
G51.4	G51.4	G51.4		Start synchronous control	
G51.5	G51.5	G51.5	00	Start composite control	
G51.6	G51.6	G51.6		Start superimposed control	
G52	G52	G52		Local coordinate system setting	
G53	G53	G53		Machine coordinate system setting	
G53.1	G53.1	G53.1		I ool axis direction control	
G53.6	G53.6	G53.6		I ool center point retention type tool axis direction control	
(G54.1)	G54 (G54.1)	G54 (G54.1)		Workpiece coordinate system 1 selection	
G55	G55	G55		Workpiece coordinate system 2 selection	
G56	G56	G56	14	Workpiece coordinate system 3 selection	
G57	G57	G57		Workpiece coordinate system 4 selection	
G58	G58	G58		Workpiece coordinate system 5 selection	
G59	G59	G59		Workpiece coordinate system 6 selection	
G54.4	G54.4	G54.4	26	Workpiece setting error compensation	
G60	G60	G60	00	Single direction positioning	
G61	G61	G61		Exact stop mode	
G62	G62	G62	15	Automatic corner override mode	
G63	G63	G63		Lapping mode	
G64	G64	G64		Cutting mode	
G65	G65	G65	00	Macro call	

G code system		0	Function		
Α	В	С	Group	Function	
G66	G66	G66		Macro modal call A	
G66.1	G66.1	G66.1	12	Macro modal call B	
G67	G67	G67		Macro modal call A/B cancel	
G68	G68	G68	04	Mirror image on for double turret or balance cutting mode	
000 1	0.00.4	0.00.4		Coordinate system rotation start or 3-dimensional coordinate	
G68.1	G68.1	G68.1		system conversion mode on	
G68.2	G68.2	G68.2	17	Tilted working plane command	
G68.3	G68.3	G68.3		Tilted working plane command by tool axis direction	
G68.4	G68.4	G68.4		Tilted working plane command (incremental multi-command)	
	0.00	G69		Mirror image off for double turret or balance cutting mode	
G69	G69		04	Cancel	
0.00 /	0.00.1	0.00.4		Coordinate system rotation cancel or 3-dimensional	
G69.1	G69.1	G69.1	17	coordinate system conversion mode off	
G70	G70	G72		Finishing cycle	
G71	G71	G73		Stock removal in turning	
G72	G72	G74		Stock removal in facing	
G73	G73	G75	00	Pattern repeating cycle	
G74	G74	G76		End face peck drilling cycle	
G75	G75	G77		Outer diameter/internal diameter drilling cycle	
G76	G76	G78		Multiple-thread cutting cycle	
G71	G71	G72		Traverse grinding cycle	
G72	G72	G73		Traverse direct sizing/grinding cycle	
G73	G73	G74	01	Oscillation grinding cycle	
G74	G74	G75		Oscillation direct sizing/grinding cycle	
0/4	0/4	015		Canned cycle cancel for drilling	
G80	G80	G80	10	Electronic dear box : synchronization cancellation	
G80.4	G80 4	G80 4		Electronic gear box: synchronization cancellation	
G81 4	G81 4	G81 4	28	Electronic gear box: synchronization start	
C80.5	G80.5	G80.5		Electronic gear box. Synchronization start	
C81 5	C81 5	G81 5	27	Electronic gear box 2 pair: synchronization cancellation	
001.5	001.0	001.0		Shot drilling (ES15-T format)	
G81	G81	G81		Electronic gear box : synchronization start	
682	<u>C8</u> 2	<u>C8</u> 2		Counter boring (ES15-T format)	
C83	C83	C83		Cycle for face drilling	
C83 1	C83 1	G03 C83 1		High-speed pack drilling cycle (ES15-T format)	
G03.1	G03.1	G03.1		High speed peck drilling cycle (FS15-1 10111dt)	
G03.0	G03.0	G03.5		Rock drilling cycle	
G03.0	G03.0	G03.0	10	Cycle for face tapping	
004	004	004	10	Divid tenning avala (ES15 T format)	
G04.2	G04.2	G04.2		Rigid tapping cycle (FS15-1 ionnat)	
G85	685	685		Cycle for face boring	
G87				List and sold drilling	
G87.5	G87.5	687.5		High-speed peck drilling cycle	
	GØ/.0		4	Peck unning cycle	
<u>G88</u>	G88	G88		Cycle for side tapping	
689	689	689		Cycle for side boring	
690	6//	G20		Outer diameter/internal diameter cutting cycle	
692	678	G21	01	Inreading cycle	
<u>G94</u>	6/9	G24		End face turning cycle	
G91.1	G91.1	G91.1	00	Maximum specified incremental amount check	

G code system			Croup	Function	
А	В	С	Group	Function	
G96	G96	G96	02	Constant surface speed control	
G97	G97	G97	02	Constant surface speed control cancel	
G96.1	G96.1	G96.1		Spindle indexing execution (waiting for completion)	
G96.2	G96.2	G96.2	00	Spindle indexing execution (not waiting for completion)	
G96.3	G96.3	G96.3	00	Spindle indexing completion check	
G96.4	G96.4	G96.4		SV speed control mode ON	
G93	G93	G93		Inverse time feed	
G98	G94	G94	05	Feed per minute	
G99	G95	G95		Feed per revolution	
-	G90	G90	02	Absolute programming	
-	G91	G91	03	Incremental programming	
-	G89	G98	11	Canned cycle : return to initial level	
-	G99	G99		Canned cycle : return to R point level	

4.7 Mill G-codes

G code	Group	Function	
G00		Positioning (rapid traverse)	
G01		Linear interpolation (cutting feed)	
G02		Circular interpolation CW or helical interpolation CW	
G03	0.1	Circular interpolation CCW or helical interpolation CCW	
G02.1, G03.1	01	Circular thread cutting B CW/CCW	
G02.2, G03.2		Involute interpolation CW/CCW	
G02.3. G03.3		Exponential interpolation CW/CCW	
G02.4. G03.4		3-dimensional coordinate system conversion CW/CCW	
G04		Dwell	
		Al contour control (high-precision contour control compatible	
G05	00	command). High-speed cycle machining. High-speed binary	
		program operation	
G05.1		Al contour control / Nano smoothing / Smooth interpolation	
G05.4		HRV3. 4 on/off	
G06.2	01	NURBS interpolation	
G07	01	Hypothetical axis interpolation	
G07 1 (G107)			
		Al contour control (advanced preview control compatible	
G08		command)	
G09	00	Exact stop	
G10	00	Programmable data input	
G10.6		Tool retract and recover	
G10.0		Programmable switching of diameter/radius specification	
G11		Programmable data input mode cancel	
G12.1		Polar coordinate interpolation mode	
G13.1	21	Polar coordinate interpolation cancel mode	
G12.4		Groove cutting by continuous circle motion (CW)	
G13.4	00	Groove cutting by continuous circle motion (CCW)	
G15		Polar coordinates command cancel	
G16	17	Polar coordinates command	
G17		XnYn plane selection	
G18	02	ZnXn plane selection	
G19	02	YnZn nlane selection	
G20 (G70)		Input in inch	
G21 (G71)	06		
G22		Stored stroke check function on	
G23	04	Stored stroke check function off	
G25		Spindle speed fluctuation detection off	
G26	19	Spindle speed fluctuation detection on	
G27		Reference position return check	
G28		Automatic return to reference position	
G28.2		In-position check disable reference position return	
G29		Movement from reference position	
G30	00	2nd, 3rd and 4th reference position return	
G30 1	00	Eloating reference position return	
G30.2		In-position check disable 2nd 3rd or 4th reference position return	
G31		Skip function	
G31.8		EGB-axis skip	

Group	Function	
· ·	Threading	
1 01	Variable lead threading	
01	Circular threading CW	
	Circular threading CCW	
	Automatic tool length measurement	
	Tool radius/tool nose radius compensation : preserve vector	
00	Tool radius/tool nose radius compensation : corner circular	
	interpolation	
	Tool radius/tool nose radius compensation : cancel	
	3-dimensional cutter compensation : cancel	
	Tool radius/tool nose radius compensation : left	
	3-dimensional cutter compensation : left	
-	Tool radius/tool nose radius compensation : right	
	3-dimensional cutter compensation : right	
1	3-dimensional cutter compensation : left (type 1)	
1	3-dimensional cutter compensation : leading edge offset	
1	3-dimensional cutter compensation : left (type 1) (FS16i-	
07	compatible command)	
] 0,	3-dimensional cutter compensation : left (type 1) (ES16i-	
	compatible command)	
4	3-dimensional cutter compensation : left (type 2)	
4	3-dimensional cutter compensation : right (type 2)	
4	2 dimensional cutter compensation : right (type 1)	
	compatible command)	
4	2 dimensional auttor companyation : right (type 1) (ES16)	
	s-dimensional cutter compensation . light (type 1) (FS for-	
-	2 dimensional author companyation i right (ture 2)	
	3-dimensional cutter compensation : right (type 2)	
	Normal direction control cancel mode	
18	Normal direction control on : left	
	Normal direction control on : right	
4	Tool length compensation +	
	Tool length compensation -	
- 08	Tool length compensation in tool axis direction	
00	Nutating rotary head tool length compensation	
	Tool center point control (type 1)	
	Tool center point control (type 2)	
	Tool offset : increase	
	Tool offset : decrease	
00	Tool offset : double increase	
1	Tool offset : double decrease	
08	Tool length compensation cancel	
	Spindle unit compensation	
27	Spindle unit compensation cancel	
	Socier concel	
	Group 01 00 07 07 18 08 08 27	

G code	Group	Function	
G50.1	22	Programmable mirror image cancel	
G51.1	22	Programmable mirror image	
G50.2	04	Polygon turning cancel	
G51.2	31	Polygon turning	
G50.4		Cancel synchronous control	
G50.5		Cancel composite control	
G50.6	00	Cancel superimposed control	
G51.4		Start synchronous control	
G51.5		Start composite control	
G51.6		Start superimposed control	
G52		Local coordinate system setting	
G53	00	Machine coordinate system setting	
G53.1		Tool axis direction control	
G53.6		Tool center point retention type tool axis direction control	
G54 (G54.1)		Workpiece coordinate system 1 selection	
G55		Workpiece coordinate system 2 selection	
G56		Workpiece coordinate system 3 selection	
G57	14	Workpiece coordinate system 4 selection	
G58		Workpiece coordinate system 5 selection	
G59		Workpiece coordinate system 6 selection	
G54.2	23	Rotary table dynamic fixture offset	
G54.4	33	Workpiece setting error compensation	
G60	00	Single direction positioning	
G61		Exact stop mode	
G62	45	Automatic corner override	
G63	15	Tapping mode	
G64		Cutting mode	
G65	00	Macro call	
G66		Macro modal call A	
G66.1	12	Macro modal call B	
G67		Macro modal call A/B cancel	
0.00		Coordinate system rotation start or 3-dimensional coordinate	
G68		conversion mode on	
000		Coordinate system rotation cancel or 3-dimensional	
G69	16	coordinate conversion mode off	
G68.2		Tilted working plane command	
G68.3		Tilted working plane command by tool axis direction	
G68.4		Tilted working plane command (incremental multi-command)	

G code	Group	Function	
G70.7		Finishing cycle	
G71.7		Outer surface rough machining cycle	
G72.7		End rough machining cycle	
G73.7		Closed loop cutting cycle	
G74.7	00	End cutting off cycle	
G75.7		Outer or inner cutting off cycle	
G76.7		Multiple threading cycle	
G72.1		Figure copying (rotary copy)	
G72.2		Figure copying (linear copy)	
G73		Peck drilling cycle	
G74	09	Left-handed tapping cycle	
G75	01	Plunge grinding cycle	
G76	09	Fine boring cycle	
G77		Plunge direct sizing/grinding cycle	
G78	01	Continuous-feed surface grinding cycle	
G79		Intermittent-feed surface grinding cycle	
000		Canned cycle cancel	
G80	09	Electronic gear box : synchronization cancellation	
G80.4	24	Electronic gear box: synchronization cancellation	
G81.4	34	Electronic gear box: synchronization start	
G80.5	0.1	Electronic gear box 2 pair: synchronization cancellation	
G81.5	24	Electronic gear box 2 pair: synchronization start	
C01	00	Drilling cycle or spot boring cycle	
Gol	09	Electronic gear box : synchronization start	
G81.1	00	Chopping	
G82		Drilling cycle or counter boring cycle	
G83		Peck drilling cycle	
G84		Tapping cycle	
G84.2		Rigid tapping cycle (FS15 format)	
G84.3	00	Left-handed rigid tapping cycle (FS15 format)	
G85	09	Boring cycle	
G86		Boring cycle	
G87		Back boring cycle	
G88		Boring cycle	
G89		Boring cycle	
G90	03	Absolute programming	
G91	05	Incremental programming	
G91.1		Checking the maximum incremental amount specified	
602	00	Setting for workpiece coordinate system or clamp at	
032	00	maximum spindle speed	
G92.1		Workpiece coordinate system preset	
G93		Inverse time feed	
G94	05	Feed per minute	
G95		Feed per revolution	
G96	13	Constant surface speed control	
G97	10	Constant surface speed control cancel	

G code	Group	Function	
G96.1		Spindle indexing execution (waiting for completion)	
G96.2	00	Spindle indexing execution (not waiting for completion)	
G96.3	00	Spindle indexing completion check	
G96.4		SV speed control mode ON	
G98	10	Canned cycle : return to initial level	
G99	10	Canned cycle : return to R point level	
G107	00	Cylindrical interpolation	
G112	21	Polar coordinate interpolation mode	
G113	21	Polar coordinate interpolation mode cancel	
G160	00	In-feed control cancel	
G161	20	In-feed control	

5 Operation

5.1 Starting NCGuide

Before starting NCGuide, the hardware key supplied with the product must be installed in a USB port on the PC, or the License Key Authorize Setting utility must be used to provide access a network license.

From the Windows Start menu, select the NCGuide program for the CNC model you wish to use. There is a program structure under FANUC NCGuide for each of the CNC models installed. The display bellow is typical of a Windows 7 display.



When the select machine composition dialog box is displayed, select either Lathe or Machining. Note that addition machine compositions may be created to configure specific CNC configurations.

Select machine composition	X
List of machine composition :	
Lathe Machining	ок
	Cancel
,	

NCGuide will now start.

5.2 Components

Component	Function	
CNC display	Show the CNC screens	
Horizontal/vertical soft keys	Clicking them allows you to perform their corresponding soft key operations. The vertical soft keys are not available on the 0 <i>i</i> MODEL D controls.	
MDI keys	Clicking them allows you to perform corresponding MDI operations	
Mini operator panel	Click the buttons allows you to perform the functions associated to individual keys	
Special key	Combined-key operations are executed using this special key	

5.2.1 0*i*-D components



5.2.2 30*i*, 31*i* and 35*i* components

	CNC disp	lay
FANUC Series 31/-MODEL B	-/	C
ACTUAL POSITION ABSOLUTE X 0.000 Y 0.000 Z 0.000	NOOO1 NOOO00 HIGHTINE DISTRINCE TO GO B. BHB X B. BHB	
HUDPL HUDPL HUDPL H <	F 0HEVATIN S 0.711N WARTS COUNT 40 WARTS COUNT 64524455 VYCLE TINE 64 64 65 A2. HEM 09:38:58 HEM 04 65 A2.	 Vertical soft keys
		Horizontal soft keys
	G H J K L 4 5 B N M ∞ 1 2 1 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	6 MDI keys
Mini operator	panel	Special key

5.3 CNC Mode selection

CNC operation is determined by selecting the CNC mode. The modes supported by NCGuide are EDIT, AUTOMATIC (MEM) and MDI. The mode can be selected with mini operator's panel displayed by NCGuide.

The active mode is displayed in the lower right of the CNC screen.



5.3.1 EDIT - Program editing mode

The following program editing operations are possible.

- 1. Creating new part programs
- 2. Editing part programs
- 3. Deleting part programs

5.3.2 MEM – Memory operation

The part programs registered in the CNC memory can be executed.

5.3.3 MDI operation mode

Part program blocks can be entered and executed using the MDI keys.

5.4 MDI key operation

The MDI keys may be used in the same way as those on an actual CNC, either by using a mouse or a touch screen. Though the MDI key panel layout may change depending on the CNC model or when the display size is changed, the components are readily identifiable.



5.4.1 MDI keys

Key(s)	Function	PC keyboard
Reset key	Reset the CNC	Esc
Help key	Detailed information on how to operate the CNC is displayed	Home
Function keys	Selects the CNC screens	
POS	CNC position screen is displayed	Ctrl-r
PROG	Part program screen is displayed	Ctrl-p
OFS/SET	Offset or setting screens are displayed	Ctrl-o
MESSAGE	Alarm screen is displayed	Ctrl-m
GRAPH	Graphic screen is displayed	Ctrl-g
CUSTOM1	Not used by NCGuide	n/a
CUSTOM2	Not used by NCGuide	n/a
SYSTEM	Parameter or diagnostic screens are displayed	Ctrl-s
Numeric keys	Allow numerical values to be entered	Numeric keys 09
Input key	Data in edit key buffer is entered in CNC	Enter
Cancel key	Data in edit key buffer is cancelled	Backspace
Address keys	Allows letter address characters to be entered	Letter keys AZ
Cursor keys	Move cursor up, down, left, right on CNC	Cursor keys
Page keys	Pages screen up and down on CNC screen	Page up / page down
Edit keys	Allow the part program to be modified	
Alter key	The character or word at the cursor position is modified with the keys pressed	n/a
Insert key	The data entered is inserted at the cursor position	Insert
Delete key	The character or word at the cursor position is deleted	Del
Special key	Used for an operation that normally requires the simultaneous pressing of two keys on actual CNC. This key is not available on an actual CNC. To simulate the simultaneous pressing of two keys, first click the special key, then click the two keys in succession in any order. As soon as the second key is clicked, the corresponding function will be executed.	n/a

Note that the PC keyboard assignments can be customized using the Key Arrangement tool selectable in the NCGuide program start menu structure. Combinations of a key together with the Shift, Ctrl and Alt keys are possible.

5.5 Soft key operation

The horizontal and vertical soft keys may be used in the same way as those on an actual CNC, either by using a mouse or a touch screen. The horizontal soft keys are used to perform operations describe by the text above each key. The vertical soft keys are used as chapter selection soft keys, an alternative to the tradition function key selection. By pressing one of the vertical keys, the screen (chapter) belonging to each function can be selected. With the 10.4" screen, the text associate with each vertical key is displayed by pressing the lowermost vertical key. Note that the 0i-D control does not support the vertical soft keys.

	ANUC Series 3	II-MODEL B		
	ACTUAL POSITION ABSOL X Y Z	0.000 0.000 0.000	00001 N0000 HACHTNE X 0.000 X 0.000 X 0.000 2 0.000 2 0.000 2 0.000 2 0.000 2 0.000 2 0.000	
	H006 608 608 615 F 617 638 649,14 628 625 0 622 662 6168 1 622 662 618 1 623 637 613 15 621 654 639,1 649 664 654,28 649 669 688,5	L H	F ØHUMIN PARTS COUNT CVCLE TIME 0H52M3 CVCLE TIME 0H52M3 CVCLE TIME 0H10H10 D2_ MEH	Vertical soft keys
. [Horizontal s	soft keys



0i-D 8.4" display horizontal soft keys (no vertical available)

FANUC Series 317-MODEL B		
BC:00000010	TE	
00001; 690X0Y0; N1692X0Y0;	ALL	
N2691600X10.0Y4.0; N3601Y45.0F500.; N4X45.0; N6Y-40.0; N7X-49.0; N5600X-4.0;-9.0;	PROGRA	
M30; ; %	СНЕСК	
		-8
		_8
	A>>	
	HEH ************************************	

31i-B 10.4" display soft keys (with vertical text displayed)

DB0000010 PROGRM DB00000010 PROGRM NC0010000010 PROGRM NC0010000010 PROGRM NC001000010 PROGRM NC001000010 PROGRM NC0010000010 PROGRM NC0010000010 PROGRM NC0010000010 PROGRM NC0010000010 PROGRM NC0010000010 PROGRM NC001000010 PROGRM NC001000010 PROGRM NC001000010 PROGRM NC00100010000000 PROGRM NC0010000000000000000000 PROGRM NC0010000000000000000000000000000000000	PRUGRHM					00001	NAAAA	
DB011 DSMXYP: H1023X0709: H203DB0X18.0F4.0: H203DB0X54.0F300.: H30:0: HV7-49.0; HV7-49.0; HV7-49.0; HV7-49.0; H9000X-4.0Y-9.0: HEX HEX HEX HEX HEX H10 H2000X H200X SED M0 PETYPE B0 FDIT	BC: 00000010					00001	PROGR	-
NO ALARM. A>	00001: 090X0Y0; H1992X0Y0; H2991G00X10,0Y4.0; H3061Y45.0F300,; H4X45.0; H4X45.0; H7X-49.0; H7X-49.0; H7X-49.0; H730; ; %						FOLDE CHECK NEXT TTHE RESTR	
PROGRM SEARCH REVIND P-TYPE Q-TYPE D-TYPE BE BG EDIT	NO ALARM.			A>	* *** *** 110:0	2:52		
	PROGRM SEARCH SEA	NO REWIND	P-TYPE Q-TY	PE		BG EDIT		

31i-B 15" display soft keys

The PC keyboard keys to control the horizontal soft keys are F1 through F12, assigned from left to right. The PC keyboard keys to control the vertical soft keys are Ctrl-F1 through Ctrl-F9, assigned from top to bottom.

Note that the PC keyboard assignments can be customized using the Key Arrangement tool selectable in the NCGuide program start menu structure. Combinations of a key together with the Shift, Ctrl and Alt keys are possible.

5.6 Mini operator panel operation

The mini operator panel is provided with the basic operations necessary to run part programs in CNC guide. Clicking the operation keys allows you to perform CNC mode switching, cycle start and stop, single block execution and block skip. Though the visual placement of the keys may change with each display, the functions remains the same.





31i 10.4" mini operator panel



31i 15" mini operator panel

Key(s)	Function	PC keyboard
0	Exits NCGuide	
	No function, just provided for display purposes	
AUTO	Switches the CNC to auto mode	Ctrl-1
EDIT	Switches the CNC to edit mode	Ctrl-3
	Switches the CNC to MDI mode	Ctrl-2
PATH SELECT	No function in NCGuide Academic packages because they only support single path controls	
CYCLE	Cycle start the execution of a part program or MDI block	Ctrl-[
CYCLE	Stop (pause) part program execution	Ctrl-]
SINGLE BLOCK	Execute the part program one block at a time	On Ctrl- off Ctrl-^
BLOCK	Skip blocks in the part program mark with a slash '/'	

Note that the PC keyboard assignments can be customized using the Key Arrangement tool selectable in the NCGuide program start menu structure. Combinations of a key together with the Shift, Ctrl and Alt keys are possible.

5.7 Screens display

The following are examples of the common screens displayed in NCGuide.

5.7.1 Position screen

ACTUA	AL POS	SITION	TOOL	OFFSET	(000	23	NØ(200	20
		ABS	OLUTE			MACHINE		DISTAN	CE TO	GO
\sim			0	000	x	0.000)	x	0.000)
			ש		Y	0.000)	Y	0.000)
\sim			0	000	z	0.000)	Z	0.000)
			<u>ں</u>	.000						
7			0	000						
~			6	.000						
		MO	IDAL		F				Øm	M∕MIN
GØØ	680	G15 F	М		-				0	
617	698	640.1 <mark>H</mark>			S				- U /1	MIN
690	650	G25 D								
622	667	G160 T			PARTS	COUNT				59
694	697	613.1 <mark>5</mark>			RIN TI	ME			1H ·	9M AS
621	654	650.1			CYCLE	TIME			ØH	ØM ØS
640	664	654.2B								
649	009	080.5			A>_					
					MEM	**** *** *	**	15:07:4	5	
		1 1	1	1 1	0.DCO			1	COPPT	
					TE		HLL		CORKI	1
					, r E	vL				

Position screen - Series 31i 10.4" display

The current positions of each axis is displayed in the workpiece coordinate system, relative coordinate system, machine coordinate system and distance to go.

5.7.2 Program screen

PROGRAM(WORD)	
G-CUDE PUCKET EG	01200 1100000
//CNC_MEM/USER/PATH1/	
U1236 (G-CUDE PUCKET EG) ;	61 X-60. Y-46.5 ;
G1902 B130. D90. H30. 165. J45. K0. ;	63 X-70. Y-56.5 10. J-10. ;
(MILL OUISIDE WALL) ;	
111 MUD ;	60 X-74. Y-50. ;
VII ; NO2 C1000 ;	
NOJ 51000 ;	GU 2-9. ;
C42 7400 U144 .	GI 2-10, F2000, ;
C40 C90 C17 ·	G1 X-64, T-40, 10, J10, F3000, ;
CQ Y-76 5 Y-50 ·	G1 X64 Y44 ·
G0 71 ·	G1 Y64 Y-44
60 7-9 :	G1 X-60 Y-44 :
61 7-10 F2000 :	63 X-70 Y-54 IO I-10 :
G3 X-66.5 Y-40. IA. J10. F5000. :	GA 71. :
G1 X-66.5 Y46.5 ;	GØ X-76.5 Y-50. ;
G1 X66.5 Y46.5 ;	GØ Z1. ;
G1 X66.5 Y-46.5 ;	G0 Z-19. ;
	7
	A>_
	EDIT **** *** 15:14:01
	PROGRA FOLDER NEXT CHECK (OPRT) +
	M I I I I I I I I I I I I I I I I I I I

Program screen - Series 31i 10.4" display

The part program may be entered, displayed, edited and executed.

ACTUAL POSITION G-CO	DDE POCKET EG	01236	N00000
		F	
	52,000	PARTS COUNT	52
Y 40	<u>ar 100</u>	RUN TIME	1H24M335
<u> </u>	0.400	CYCLE TIME	0H 0M 09
1 7 50	18.000		
		PROG	Ram
		G3X-70. Y-54. I.O. J-10.	;
		G0Z1.;	
		G0X-76.5Y-50.;	
		G0Z1.;	
молы		602-19.;	
600 680 615 F	м	G12-20.F2000.;	E5000 ·
G17 G98 G40.1H		61X-66, 5Y46, 5E5000	1 3000. 3
690 650 625 D		G1X66. 5Y46. 5F5000. ;	
G22 G67 G160 T		G1X66. 5Y-46. 5F5000.	
694 697 613.1 <mark>5</mark>		G1X-60. Y-46. 5F5000.	
621 654 650.1		G3X-70. Y-56. 510. J-10). F5000. ;
G40 G64 G54.2B		G0Z1.;	
649 669 680.5	n l	A>_	
3 8/M			
		EDIT **** *** ***	15:15:21
ABSOLU RELATI ALL TE VE		Progra folder nex M	r Check (oprt) +

Program check screen - Series 31i 10.4" display

The program check screen provides useful information to execute the part program, displaying the part program, position data and modal information all on a single screen.

5.7.3 Setting screen

OFFSET		G-CODE POCK	ET EG	0123	6	N00000
	CLENG	тнэ	CRADI	US)		RELATIVE
NO.	GEOM	WEAR	GEOM	WEAR		X 0.000
001	0.000	0.000	152.400	0.000		Y 0.000
002	0.000	0.000	254.000	0.000		2 0.000
003	0.000	0.000	0.000	0.000		
004	0.000	0.000	152.400	0.000		
005	0.000	0.000	304.800	0.000	F	ABSOLUTE
006	0.000	0.000	76.200	0.000		X 762.000
007	0.000	0.000	0.000	0.000		Y 406.400
008	0.000	0.000	0.000	0.000		Z 508.000
009	0.000	0.000	0.000	0.000		
010	0.000	0.000	0.000	0.000		
011	0.000	0.000	4.000	0.000	ŀ	MAQUITUE
012	0.000	0.000	3.000	0.000		
013	0.000	0.000	2.000	0.000		X 702.000 X 406.400
014	0.000	0.000	0.000	0.000		7 508,000
015	0.000	0.000	0.000	0.000		2 000.000
016	0.000	0.000	0.000	0.000		
			A	>_		
						1
				EDIT **** *** **	*	15:19:04
				OFFSET SETTIN	WORK	(OPRT) +
				G		

Tool offsets and work coordinate offsets can be display and modified.

Tool offset screen - Series 31i 10.4" display



Work coordinate offset screen - Series 31i 10.4" display

Several handy settings are available to change input and output settings. Primarily the input/output will be set to the MEMCARD in NCGuide.

ACTUA	IL POSI	TION	G-CODE	e pocket	r eg		012	36	N	000	000
		AB		\sim	200	F				6) mm/min
			ſЬ	ي . ک	999	PARTS	6 COUNT				52
Y			40	6.4	100	RUN T	IME			i	l <mark>H24M</mark> 33 <mark>S</mark>
<u> </u>				.	100	CYCLE	TIME			(3h om os
			50	8.(200		SET	TING C	HANDY)	
						PARAM	IETER WRIT	E= <mark>1</mark> (0:	DISAB	LE 1:E	NABLED
						TV CH	IECK	= 0 (0:	OFF	1:0N)	
						PUNCH	I CODE	= 0 (0:	EIA	1:150)
						INPUT	UNIT	=0 (0:	MM	1:INC	Ð
						I∕0 (CHANNEL	= 4 🕻	9-35 : C	HANNEL	NO.)
		M	IODAL			SEQUE	ENCE NO.	=0(0:	OFF	1:0N)	
600	680	615 F		M		PROGR	ram format	=0(0:	NO CH	V 1:F	15)
690	650	625 D				SEQUE	ENCE STOP	=	0 <	PROGRA	M NO.)
622	G67 I	G160 T				SEQUE	ENCE STOP	=	0 <	SEQUEN	CE NO. >
G94	697 (G13. 1 <mark>S</mark>				COUT		-r. ou		-1000	
621	654	G50. 1				CUNTR	(HSI C+	-L UN	- 1 1	-LOFF	:0 1)
G40	G64	654.2 <mark>8</mark>									
649	669	680.5				A>_					
3			0/11N								
						EDIT	**** ***	***	15:23	3:04	
A T	ibsolu Te	relat i Ve	ALL			OFFS	GET SETTIN	WORK		COF	PRT> +

Setting (handy) screen - Series 31i 10.4" display

5.7.4 Parameter screen

Parameters can be set that modifies functions of the CNC.

Parame	TER			G-C	ODE	РОСК	et e	G	01236 N00000
<mark>00000</mark>	Ø	Ø	SEQ Ø	Ø	Ø	INI Ø	ISO Ø	TVC Ø	00022 INP CHANNEL/B. G.
00001	Ø	Ø	Ø	Ø	Ø	Ø	FCV Ø	Ø	00023 OUT CHANNEL/B. G.
00002	SJZ Ø	Ø	Ø	Ø	Ø	Ø	Ø	0	00024 0 00100 ENS IOP NCR CRF CTV
00010	ø	Ø	ø	Ø	Ø	PEC Ø	PRM Ø	PZS Ø	00101 NFD ASI SB2
00012 X Y	RMV Ø Ø	Ø Ø	0 0	0 0	0 0	0 0	0 0	MIR Ø Ø	0 0 0 0 0 0 0 1 00102
Z 00020	Z 00 00 00 00 00 00 00 00 00 00 00 00 00								00103 BAUDRATE CH0 10
00021	OUT	CHA	NNEL	4 /F.G ӣ					99119 104 9 9 9 9 9 9 9 9 9
	1			0					00111 NFD ASI SB2 19 19 19 19 19 19 19 19
									A>_
		Γ	1		T		T		EDIT ***** *** 15:24:25 PARAME DIAGNO SERVO SYSTEM (OPRT) + TER SIS GUIDE

Parameter screen - Series 31i 10.4" display

5.7.5 Message screen

All usual alarm and operator messages are displayed.

Alarm Message Tool Offset	00003 N00003
PS0007 ILLEGAL USE OF DECIMAL POINT	
	A>_
	MEM_STOP *** *** 14:15:25
	Alarm Messag Histry +

Alarm screen - Series 31i 10.4" display

Alarms and messages can be generated in the part program or subprograms using Custom Macro variables (#3000 Alarm, #3006 Message) to provide feedback or instructions to the student.

ACTU	IAL POSI	ITION	1	TOOL	DFFSET	00	003	NØ	0000
	ı.	AB	SOLUTE	1	050	F			
			J	4.	300	PARTS COUN	IT		49
ΙY			1	Ρ.	017	RUN TIME			0H56M51S
<u> </u>			-	Ξ .		CYCLE TIME			OH OM OS
7				Й.	000		OPERATOR	MESSAGE	
						EXECUTE IN AT END OF	i single ani Each block) NOTE P	OSITIONS 🛕
_		M	IODAL			1			
600	680	G15 F		M	30				
617	698	G40.1H							
690	650	625 J							
694	697	613 1 C							
621	654	650.1							
G4Ø	G64	G54.2B							
649	G69	G80. 5							<u> </u>
S			0/MIN			H>_			
						MEM STOP	*** ***	14:40:1	11
	absolu Te	relati Ve	ALL			alarm me	ESSAG HISTR	Υ	

Operator message generated with #3006 Custom Macro - Series 31i 10.4" display

5.7.6 Graphic screen



Graph screen - Series 31i 10.4" display

5.8 Editing part programs

5.8.1 Creating part programs

Before you can enter a part program through the MDI key panel, it must be registered. For example, the procedure to register the part program number O1234 is as follows:

- 1. Select EDIT mode.
- 2. Press the PROG function key.
- 3. Press the 'O' letter address key.
- 4. Press the '1', '2', '3' and '4' numeric keys in order.
- 5. Press the INSERT key.
- 6. Press the EOB (end of block) key.
- 7. Press the INSERT key.
- 8. "O1234" is displayed on the screen. Note that the "%" end of program marker is generated automatically.
- 9. Now you can add blocks to the registered part program.

Program(Word)	01234 N00011
//CNC_MEM/USER/PATH1/	
01234 (FG-EDIT)	
01234 ;	A
7.	
	EDIT STOP *** *** 16:22:10
< PROGRM LINE SELECT PASTE	SEARCH REPLCE 1 +
SEARCH SEARCH	SEARCH SEARCH

Registering part program '01234' screen - Series 31i 10.4" display

5.8.2 Altering a word

The procedure for altering a word is as follows:

- 1. Select the EDIT mode.
- 2. Press the PROG function key.
- 3. Move the cursor to the word to be altered using the page and cursor keys.
- 4. Use the address and numeric keys to enter the new text in the input buffer.
- 5. Press the ALTER key to replace the selected word with the text in the input buffer.

5.8.3 Inserting a word

- 1. Select the EDIT mode.
- 2. Press the PROG function key.
- 3. Move the cursor to the word before the position you want to insert new text using the page and cursor keys. Note to add a new block, position the cursor on the EOB symbol ';' at the end of the block prior to the insertion point.
- 4. Use the address and numeric keys to enter the new text in the input buffer. If adding a complete new block, do not forget to include a new EOB symbol ';'.
- 5. Press the INSERT key to insert the selected word/text you typed in the input buffer.

5.8.4 Deleting a word

- 1. Select the EDIT mode.
- 2. Press the PROG function key.
- 3. Move the cursor to the word you want to delete using the page and cursor keys.
- 4. Press the DELETE key to delete the selected word.
- 5. Repeat the process to delete multiple words.

5.9 Selecting part programs

Once part programs have been registered in the CNC, they can be selected by the following two methods:

- 1. Selection using the program call operation.
- 2. Selection from the program list. (not available in 0i-D)

5.9.1 Selection using program call operation

The procedure for selecting part programs using the program call operations is as follows:

- 1. Select EDIT or AUTO (MEM) mode.
- 2. Press the PROG function key.
- 3. Enter the program number you want to select using the address and numeric keys.
- 4. Press the CURSOR DOWN key.
- 5. The active part program is changed. If the part program is not registered, the warning "SPECIFIED PROGRAM NOT FOUND" is displayed below the input buffer on the CNC screen.

5.9.2 Selection using the part program list

The procedure for selecting part programs using the part program list is as follows:

- 1. Select EDIT or AUTO (MEM) mode.
- 2. Press the PROG function key.
- 3. Press the soft key [FOLDER]
- 4. Move the cursor to the part program to select using the cursor keys.
- 5. Press the soft key [(OPRT)]

6. Press the soft key [MAIN PROGRAM].

5.10 Deleting part programs

Once part programs have been registered in the CNC, they can be deleted by the following two methods:

- 1. Deletion using the program call operation.
- 2. Deletion from the program list. (not available in 0*i*-D)

5.10.1 Deletion using program call operation

The procedure for deleting part programs using the program call operation is as follows:

- 1. Select EDIT or AUTO (MEM) mode.
- 2. Press the PROG function key.
- 3. Enter the program number you want to delete using the address and numeric keys. For example to delete "O0001", enter 'O', '0', '0', '0' and then '1' in order, or just 'O' and then '1' (lead zeros are not required).
- 4. Press the DELETE key. The following message is displayed "DELETE PROGAM (O0001) ?"
- 5. Press the soft key [EXEC] if you want to confirm the program deletion, otherwise click the soft key [CAN] to cancel the deletion operation.

5.10.2 Deletion using the part program list

The procedure for deleting part programs using the part program list is as follows:

- 1. Select EDIT or AUTO (MEM) mode.
- 2. Press the PROG function key.
- 3. Press the soft key [FOLDER]
- 4. Move the cursor to the part program to delete using the cursor keys.
- 5. Press the soft key [(OPRT)]
- Press the soft key [DELETE].
 The following message is displayed "DELETE PROGAM ?"
- 7. Press the soft key [EXEC] if you want to confirm the program deletion, otherwise click the soft key[CAN] to cancel the deletion operation.

5.11 Part program execution

5.11.1 Part program execution

Part programs can be executed in MEM (auto) mode and checked with the graphic function.

- 1. Select the AUTO (MEM) mode.
- 2. Click the PROG key.
- 3. Check that the cursor position is at the top of the part program screen. If not, click the soft key [(OPRT)] and then click the soft key [REWIND].
- 4. Click CYCLE START.

5.11.2 Program graphic function check

- 1. Select the AUTO (MEM) mode.
- 2. Click the PROG key.
- 3. Check that the cursor position is at the top of the part program screen. If not, click the soft key [(OPRT)] and then click the soft key [REWIND].
- 4. Click the GRAPH key.
- 5. Press the soft key [(OPRT)] (this step is not necessary in the 0*i*-D version)
- 6. Press the soft key [START] (this step is not necessary in the 0*i*-D version)
- 7. Click CYCLE START.

5.11.3 Single block execution

When SINGLE BLOCK is active, program blocks are executed one block at a time. CYCLE START must be clicked for each block. To activate SINGLE BLOCK, click the SINGLE button on the mini operator panel. To deactivate SINGLE BLOCK, click the SINGLE button on the mini operator panel again.

5.12 Multi-language display

The following languages are supported by the CNCs and NCGuide.

- Chinese (simplified)
- Chinese (traditional)
- Czech
- Danish
- Dutch
- English
- French
- German
- Italian
- Hungarian
- Japanese
- Korean
- Portuguese
- Russian
- Spanish
- Swedish
- Turkish

5.12.1 Language switch procedure

- 1. Click the OFS-SET function key.
- 2. Click the continuous menu key several times until the [LANGUAGE] soft key text is displayed.
- 3. Click the soft key [LANGUAGE] to display the language screen.
- 4. Click the page and cursor keys to move the cursor to the desired display language.
- 5. Click the soft key [(OPRT)].
- 6. Click the soft key [APPLY]. The display is switched to the selected language, which remains active even if the CNC is turned off and on.

CORRE	EC		т	ool ofi	FSET	0	000	23	N000	00
		AB	SOLUT			F			Ø	
X			1	0.0	700		. 0700			
10				2.7	222		PZH5 TIM		14	25 7M140
Υ I			l l	ا• ك	200	TMPO C			ØH	OM 05
7			1	a (ิลดด			IDIO	MA	
~				U • 4	000	SELECO	IDIOMA A	A VISU	ALIZAR	
						астна	: ESPE	niñe		
						TNG	ÉS - ENGL	ISH		
						JAPO	NÉS - 172	本語		
						ALEM	án – Deut	SCH		
		М	odal			FRAN	C - FRANC	AIS	-	
GØØ	G80	G15 F		M		CHIN	U ІКНУ — П СТМРІТЕ	UNINES	∟ 泣今	
617	698 CE0	G40.1H				ITAL	IAN - ITA	LIANO	- 12, 1	
622	667	625 J				CORE	AN - 한국	0		
694	697	G13.15				* <mark>ESPA</mark>	ñol			
621	654	G50.1				HOLA	ND - NEDE	RLANDS	;	
640	664	654. 2 <mark>B</mark>				DANE	s - DANIS	iΗ		
649	669	680.5	-							
5			0/MIN							
						MEM *	*** *** *	**	10:52:09	
< [IBSOLU	RELATI	TOD				APLIC	Ύ		

Setting the display language screen - Series 31i 10.4" display

5.13 Exiting NCGuide

There are several methods to exit NCGuide

In picture mode:

- Click the "Off" button on the mini operator panel
- Right-click anywhere on the CNC and select Exit from the popup menu.

In window mode:

• Select Exit from the File menu.

6 MANUAL GUIDE *i*

6.1 What is MANUAL GUIDE *i*

MANUAL GUIDE *i* is an easy-to-use yet powerful conversational part programming and operation environment. It guides operator's on how to program and operate CNC controls installed on machine tools such as lathes and machining centers. It features a single screen that can be used to create machining part programs, check them using animation, set up tooling and workpieces, and perform the actual machining.

MANUAL GUIDE *i* programs are high-level G-code programs using advanced machining cycles. They can be quickly converted to lower-level G-code programs that will run on a wide range of FANUC CNC models.

6.2 Academic applications of MANUAL GUIDE *i*

NCGuide provides a powerful environment to learn about conversational part programming. Conversational program is rapidly replacing manual machining in many toolrooms and some job shops because it provides more flexibility, accuracy and speed yet still uses journeyman knowledge and skills to create parts directly from the workpiece drawing.

Conversational programming allows the student to learn processes and sequence of operations rather than focus on the specific G-codes used.

MANUAL GUIDE *i* also provides fixed sentence programming to generate multiple lines of G-code with just a few keystrokes. Fixed sentences can be established for sequence of operations such as program starting blocks, tool change blocks, material feeds and speeds and part program end blocks.



6.3 Main Features of MANUAL GUIDE *i*

Integrated operation screen that facilitate most routine machining operations
 A single integrated operation screen provides for routine machining operations including
 machining part program input/editing, animated simulation based machining program
 checks, production machining and MDI operations. Manual operations with JOG and
 HANDLE are also supported (not in NCGuide).

• Simple part program generation Simple menu-driven conversation programming screens guide the operator through a series of common machining operations. These high-level operations eliminate the trouble of repeatedly generating the same multiple blocks of G-code.

• Realistic animated simulation

Machining programs can be checked easily using the 3D solid model animated simulation for all operations for both milling and turning. It realistically shows the surface being removed with a specific type of tool tip as if a real workpiece is being machined.

• Advanced machining using machining cycles Advanced milling machining cycles are available to perform complex machining, but the conversation environment makes creating and running these programs easy.

• Machining programs in G-code format

Common G-code is also supported by MANUAL GUIDE *i* part programs, which enables the operator to specify simple operations such as straight lines and arc with simple G-code commands, and the more complicated machining operations using the advanced machining cycles.

• Affinity with CAD/CAM

Machining programs created using CAD/CAM can be still be used without modification. Adding advanced machining cycles to these machining programs makes them perfect machining programs. They can be checked easily, using animated simulation.

Advanced machining program editing

Using advanced editing functions, such as substring search and cut/paste via the clipboard, enables easy editing of machining programs.

M-code menu

It is possible to input M codes easily by referencing explanations displayed in an M code menu. Machine tool builders can create the explanations easily.

Advanced set-up guidance (option)

It is possible to set up machining operations to ensure the precision machining easily. Using an advanced set-up guidance functions all measurements can be easily taken, from tool offset measurement through to the measurement of the workpiece. (not supported by NCGuide)

• Wide support for various machining centers

The 3+2 axis machining center with a tilting head as well as vertical and horizontal machining centers are supported.

6.4 Navigation to MANUAL GUIDE *i*

6.4.1 Starting MANUAL GUIDE *i*

- 1. Select NCGuide from the Windows menu.
- 2. Select a machine composition that includes MANUAL GUIDE *i* then click the OK button.

Select machine composition	X
List of machine composition :	
Lathe Machining Machining Manual Guide i	ок
	Cancel

3. Click the GRAPH function key on the CNC when start up is complete.

FANUC Series 317-MODEL B
MANUAL GUIDE i (CAC_HER/USER/PATH1) Gef 13:25:39 ACTUAL PDS. (ABS.) DIST TO GU SP1NDLE S1 X 0.000 CAC 0.000 Y 0.000 SP1NDLE S1 Y 0.000 SP1NDLE S1 Y 0.000 SP1NDLE S1 P 0.000 SP1NDLE S1 Y 0.000 SP1NDLE S1 B: 0.000 SP1NDLE S1 P 0.000 S91NDLE S1 B: 0.000 S1 S1 CB0 1.00033 CI0AL OFFSET); S2 CB0 X 0.000 CI0AC OFFSET); S1 CB1 000033 CI0AL OFFSET); S1 S1 CB2 0.000 S1 S1 S1 S1 CB2 0.000 CI0AC OFFSET); S1 S1 S1 CB2 0.000 S1 S1 S1 S1 S1
S NS GED X0 Y0 : M GAL D01 : ? 7 NS MSD P100 ; 9 H7 GSD X0 Y0 : 10 H6 GAD ; 9 H7 GSD X0 Y0 : 11 H9 H99 P100 ; 12 H10 GAD ; 11 H9 H99 P100 ; 12 H10 GAD ; 12 H10 GAD ; 12 H10 GAD ; 13 H9 H99 P100 ; 14 H7 CSD ; 15 H10 GAD ; 16 H10 GAD ; 17 H10 GAD ; 18 H10 GAD ; 19 H10 GAD ; 10 H11 H9 H99 P100 ; 11 H9 H99 P100 ; 12 H10 GAD ; H10 GAD ; H11
$\begin{array}{c c c c c c c c c c c c c c c c c c c $

6.4.2 MANUAL GUIDE *i* screen components

All part programming and operation is achieved from a single primary screen. When additional inputs are required from the operator/part programmer, popup screens are displayed.



Component	Function		
Machine information	 Axis positions Distance to go Spindle speed and direction Spindle load Feed rate Modal G-codes 		
Simulation	 Simulation of part program execution 2D or 3D Solid model or tool path wire frame 		
Part program	Part program being executed or edited		
Soft keys	All navigation from these keys		

6.5 Overview of creating a MANUAL GUIDE *i* part program

A MANUAL GUIDE *i* program is created in the following steps. This follows planning session to define the operations and sequence required to make the part and deciding which tools to use.

- 1. Analyze the workpiece drawing and determine blank size, geometry and material type, determine a sequence of operations, select tooling to be used and calculate feeds and speeds.
- 2. Define part blank size (required for part program machining simulation)
- 3. Select the program start conditions (modal G-codes)
- 4. Move to the tool-change position, select tool, start spindle, coolant, set tool length offset move to the part approach position
- 5. Select a machining cycle (e.g. pocketing, drilling, slot milling) and define cutting conditions and feature geometry.
- 6. Repeat steps 4 and 5, to add additional machining processes for part features
- 7. Select program end conditions

Example

(define the part blank) G1902 B100. D100. H30. I0. J0. K1.;

```
(select a new tool)
G0 Z300.;
                          (retract Z)
X100. Y100.;
                          (move X/Y to the tool change position)
                          (select the next tool)
T1;
M6;
                          (change tool)
S1200 M3;
                          (start the spindle)
                          (start the coolant)
M08;
G43 H1 D1;
                          (activate tool length and radius offsets)
                          (approach the workpiece for the cycle)
X-25. Y-25.;
                          (move Z to the working plane)
G0 Z2.;
```

(part feature operation) (cycle cutting conditions) G1020 T1. L38. F200. E150. W2. P2. V0. C1. M1. A1. B4. Z2. I100.; (cycle part feature geometry) G1220 T1. B0. H50. V50. U100. W100.;

```
(end the part program)
M09; (turn off coolant)
G0 Z300.; (retract the Z axis)
X-100. Y-100.; (move X/Y to a safe position)
T0; (cancel tool offsets)
M30; (end and rewind the part program)
```

Note that many of these steps can be repetitive. For example, step 11 may define many "boiler plate" G-codes to end a part program, turning off coolant, moving the axis to a safe position so the operator can get access to the part, turning off offsets, and rewinding the part program (M30).

Similarly, steps 2 through 5 define those required to make a safe tool change:

```
GO Z300.;
                          (retract Z)
X100. Y100.;
                          (and move X/Y to the tool change position)
T1;
                          (select the next tool)
M6;
                          (change tool)
S1200 M3;
                          (start the spindle)
                          (start the coolant)
M08;
                          (Activate tool length and radius offsets)
G43 H1 D1
X-25. Y-25.;
                          (approach the workpiece for the cycle)
G0 Z2.;
```

These common repetitive code sections may encapsulated and inserted into the part program in a single step using the Fixed Form Sentence feature in MANUAL Guide *i*, simplifying part program creation.

Note that the only true unique parts of a part program are typically those that define the cutting conditions and the geometric properties of a part feature.

6.6 Notes on creating part programs

This section provides notes on creating part programs. Read the notes before creating a part program.

6.6.1 Commands required before machining cycle input

- 1. For milling controls, a cutter radius offset using the D letter address, even if cutter radius compensation is not used. This selects the tool geometry for 3D solid model animation.
- 2. Be sure to enter a spindle rotation command, and specify whether to enable or disable constant surface speed control.
- 3. No feed rate command needs to be specified in startup blocks, because feed rate commands are included in the machining cycles. However, specify a command for feed per revolution or feed per minute as required. For example, operator know-how on executing milling in pocketing by feed per revolution can be used.
- 4. Enter an M-code for switching between the spindle and C-axis, and a command for C-axis reference position return as required.
- 5. Enter M-codes such as for coolant ON/OFF as required.
- 6. Upon completion of machining cycle, the tool always returns to the position is was before the start of the machining cycle. By setting bit 7 (ESC) of parameter No. 27002 to 1, the tool can be prevented from returning to the position before the start of the machining cycle.

6.6.2 Machining cycles

- 1. Specify an I point coordinate not as a distance from point R but as a coordinate value.
- 2. Figure data should be entered as a subprogram for utilization in roughing, finishing, and chamfering. This eliminates the need to enter figure data each time.
- 3. In machining of a projected portion (island figure), efficient machining can be achieved by using pocketing with an island instead of using contouring. In this case, specify a blank as the outer wall of a pocket.
- 4. In contouring (side facing), enter a start point figure and end point figure so that both figures contact each other. This means that by starting not from a corner of a figure but from an intermediate point on a straight line, undercutting due to approaching the figure and retraction can be eliminated.

7 Machine compositions

A machine composition is a collection of settings that define a particual CNC system to be simulated. It define the machine type to be milling or turning. It also defines the machine axis configuration.

You can create multiple machine compositions and switch between them as necessary. The instructor may predefine a machine composition, select options, set parameters and load part programs and distribute that machine compositions to students as a platform for exercises or homework assignments.

Machine compositions may be established to closely match CNC on actual machines, CNCs not actually available to expand the student's experience, or to present problem solving situations.

The files that represent the machine composition can be archived and distributed freely. The Machine Composition Setting tool creates these five files when a new or copy machine composition action is taken.

Each CNC system to be simulated can be customized using:

- The Machine Composition Setting tool
- The Option Settings tool
- CNC parameters

7.1 Machine Composition setting tool

The Machine Composition Setting tool allows you to specify the following parameters depending on the CNC model:

CNC	System Type	Axes	MGi	
31i-MODEL A	Only at creation Only at edit		Creation and edit	
30i/31i-MODEL B	Only at creation	Only at creation Only at edit		
0i-MODEL D	Only at creation	n/a	Creation and edit	
35i-MODEL B	n/a	Creation and edit	n/a	

The machine composition tool can create, copy, edit and delete machine compositions. NCGuide does not have to be running to use the machine composition tool. The USB or network license key is necessary to use the Machine Composition Setting tool.

The Machine Composition Setting tool also makes it possible to select one machine composition as the default – it will be used whenever the NCGuide simulator is started for that CNC model. Alternatively, the user can be presented a list of machine compositions to choose from when the NCGuide simulator is started for a CNC model.

7.2 Option Setting

In the NCGuide Academic package, a basic option set is pre-initialized, therefore the following operations will typically not be necessary. However, sometime an options may have to be activated, for example, when MANUAL GUIDE i is activated using the Machine Composition Setting tool.

The options available are dependent on the machine model.

NCGuide must be running to change the option settings for a particular machine composition. In the procedures below, make sure you select the Option Setting tool for the CNC model that is running.

In NCGuide options are activated and deactivated using the Option Setting tool.

🖇 Option Setting		
PACKAGE		
PACKAGE 1		
O PACKAGE 2		
CNC		
Chic		
Option name	J-No.	
☑ 2ND. AUXILIARY FUNCTION		
✓ 3RD./4TH. REFERENCE RETURN		_
ADD. COMMON MACRO VALUE		
AXIS CONTROL BY PMC		
AXIS CONTROL DETACH		
BACKGROUND EDITING		
BASIC OPERATION PACKAGE 2 FUNCTION	A02B-0207-J814	
CANNED CYCLE FOR DRILLING		
CHAMFERING/CORNER R		
CHINESE DISPLAY		
CHUCK/TAIL STOCK BARRIER		
CONTROLLABLE AXES EXPANSION		
CUSTOM MACRO		
CYLINDRICAL INTERPOLATION		_
CZECH DISPLAY		_
✓ DANISH DISPLAY		
I DIRECT DRAWING DIMENSION		-
HATTER HED AV		
Courth		
		ancer

7.3 Parameters

Setting parameters is exactly the same in NCGuide as on the real CNC. Refer to the relevant parameter manual for the specific control type. The parameters set in NCGuide as shipped should be fine for most situations.

8 NCGuide Academic packages

8.1 System requirements

Operating systems

- Windows 2000 (Service Pack 4)
- Windows XP Home/Professional Edition
- Windows Vista Business (Service Pack 2)
- Windows 7 Professional

The following packages are also required

- .NET Framework 1.1 (Service Pack 1) *
- .NET Framework 2.0 (Service Pack 1)

Hardware system

- CPU Pentium4 1.3GHz or higher (Pentium4 2GHz or higher recommended) or Intel Core Duo 1.83GHz or higher
- Memory 256 MB or greater
- Free hard disk space 800MB or greater (about 200MB per CNC model)
- Display resolution 1280 x 1024 (SXGA) or higher
- DVD drive
- USB port

Windows NT, Windows 2000, and Windows XP, Windows Vista are trademarks of Microsoft Corporation in the United States.

Microsoft, Windows, and .NET Framework are registered trademarks of Microsoft Corporation in the United States.

Pentium is a registered trademark of Intel Corporation in the United States.

8.2 Differences from the CNC in operation

The functions of NCGuide Academic packages differ from the actual CNC as follows:

- Only EDIT, MEM, and MDI modes are selectable.
- The following functions are not supported.
 - Functions requiring the hardware of the CNC or related to it
 - Data server
 - Serial communication
 - Ethernet communication
 - Servo/spindle control
 - Option board functions such as customers' and C language boards
 - Operation History
 - Maintenance screens cannot be displayed or manipulated.
 - FANUC PICTURE
 - o C-executor
 - o Macro Executor
 - PMC simulation
 - o Machine Signal Simulation
- Interpolation commands other than G00, G01, G02 and G03 approximate to a G01 command for execution.
- The cycle time of part program operation differs from that of the actual CNC.

9 Summary

Training students on the latest FANUC CNCs is challenging. Class size, safety concerns, CNC and machine tool costs typically limit the amount of hands experience available to the individual student. NCGuide and NCGuide Academic packages provide a realistic operation and part programming environment at a fraction of the cost of using a real machine tool. Comprehension and retention is enhanced as students perform repetitive hands-on exercises in an ergonomically friendly environment - away from the noise of the workshop. Operator, G-code programming and CAM programming students can practice common procedures and test part programs without risks to people, tooling or machines.

FANUC America Corporation 1800 Lakewood Boulevard Hoffman Estates, IL 60192 888-FANUC-US (888-326-8287) Find more information at www.fanucamerica.com

Technical data is subject to change without prior notice. No part of this document may be reproduced in any form. All rights reserved. © 2013 FANUC FA America Corporation