

Table of Contents

Preface 9

- Prerequisites 9
 - Basic machining practice experience 9
- Controls covered 10
- Limitations 10
 - Programming method 10
 - The need for hands-on practice 10
- Instruction method 11
 - Scope 11
 - Key Concepts approach 11
 - Lesson structure 12
 - Practice makes perfect 12
- Key Concepts and lessons 12
 - Enjoy! 12

Key Concept 1: Know Your Machine From A Programmer's Viewpoint 13**Lesson 1: Machine Configurations 15**

- Types of CNC turning centers 15
 - Universal style slant bed turning center 15
 - Directions of motion (axes) for a universal style slant bed turning center 16
 - Live tooling for a universal style slant bed turning center 17
 - Other types of CNC turning centers 19
 - Chucking style slant bed turning center 19
 - Twin spindle horizontal bed turning centers 20
 - Sub-spindle style turning centers 21
 - Vertical single spindle turning centers 22
 - Twin spindle vertical turning centers 23
 - Gang style turning centers 23
 - Swiss-type CNC turning centers (also called sliding headstock turning centers) 24
- Programmable functions of turning centers 24
 - Spindle 24
 - Spindle speed 24
 - Spindle activation and direction 25
 - Spindle range 25
 - Feedrate 26
 - Turret indexing (tool changing) 27
 - Turret station and offset selection 28
 - Coolant 28
- Other possible programmable functions 28
 - Tailstock 28
 - Programmable steady rest 29
 - Bar feeders and chuck activation 29
 - Part catcher 29
 - Tool touch off probe 29
 - Automatic tool changing systems 30
- Exceptions to X axis 30
 - A quick fix 30
 - Gang style turning centers with cutting tools on both sides of the spindle centerline 30
 - Center cutting axis 31
- What else might be programmable? 31

Key points for Lesson One: 31

Lesson 2: Understanding Turning Center Speeds and Feeds 33

- The machining operation to be performed 33
- The material to be machined 33
- The material of the cutting tool's cutting edge 33
- The two ways to select spindle speed 34
 - When to use constant surface speed mode 35
 - When to use rpm mode 36
 - How fast will the spindle be running when constant surface speed is used? 37
 - How fast can the spindle rotate? 37
 - How to specify a maximum speed for the constant surface speed mode 38
 - A potential limitation of constant surface speed 38
- The two ways to specify feedrate 39
 - When to use the feed per revolution mode 39
 - When to use the feed per minute feedrate mode 40
- An example of speed and feed usage 40
- Key points for Lesson Two: 41

Lesson 3: Visualizing The Execution Of A CNC Program 43

- Program make-up 44
 - Method of program execution 44
 - An example of program execution 44
 - The CNC program to machine the 2.875 diameter 45
 - Sequence numbers 46
 - A note about decimal point programming 46
 - A decimal point tip 47
 - Other mistakes of omission 47
 - Modal words 47
 - Initialized words 47
 - Letter O or number zero? 47
 - Word order in a command 48
- Key points for Lesson Three: 48

Lesson 4: Program Zero And The Rectangular Coordinate System 49

- Graph analogy 49
- More about polarity 50
- Wisely choosing the program zero point location 51
 - In X 51
 - In Z 51
- Absolute versus incremental positioning movements 56
 - Another way to specify absolute and incremental positioning 56
 - A decimal point reminder 57
- Key points for Lesson Four: 58

Lesson 5: Introduction To Programming Words 61

- Words allowing a decimal point 61
- O 62
- N 62
- G 62

X	62
Y	62
Z	62
U	63
W	63
C	63
R	63
I & K	63
F	63
E	63
S	64
T	64
M	64
P	64
Q	64
L	64
EOB (end of block character)	65
/ (slash code)	65
G and M codes	65
G codes	65
G code limitation:	65
Option G codes	65
What does initialized mean?	66
What does modal mean?	66
The most popular G codes	66
Common M codes used on a CNC turning center	67
Key points for Lesson Five:	68
Key points: Key Concept one, Know your machine from a programmer's viewpoint	69
Key Concept 2: You Must Prepare To Write Programs	71
Preparation and time	71
Preparation and safety	72
Typical mistakes	73
Syntax mistakes	73
Motion mistakes	73
Mistakes of omission	73
Process mistakes	74
Lesson 6: Preparation Steps For Programming	75
Prepare the machining process	75
Develop the needed cutting conditions	77
An example	78
Roughing tools	78
Drilling	79
Finishing tools	79
Chasing threads	79
Cutting conditions can be subjective	79
Do the required math and mark-up the print	80
Other ways to come up with coordinates	83
Marking up the print	83
Doing the math	84
Check the required tooling	86
Plan the work holding set-up	87
Other documentation needed for the job	88
Production run documentation	89

Program listing	89
Is it all worth it?	89
Key points for Lesson Six:	89

Key Concept 3: Understand The Motion Types 93

What is interpolation?	93
------------------------	----

Lesson 7: Programming The Three Most Basic Motion Types 97

Motion commonalties	97
Understanding the programmed point of each cutting tool	97
G00 Rapid motion (also called positioning)	101
What is a safe approach distance?	102
What about feed-off distance?	103
G01 linear interpolation (straight line motion)	104
Using G01 for a fast feed approach	106
G02 and G03 Circular motion commands	107
Specifying a circular motion with the radius word	107
Circular motion with directional vectors (I and K)	109
What's wrong with this picture?	110
Key points for Lesson Six:	113

Key Concept 4: Know The Compensation Types 115

More on interpreting tolerances	115
What if a measured dimension is not on-size (not acceptable)?	116
The target value	117
Another consideration – tool wear	117
Do you really want to target the mean value?	118

Lesson 8: Introduction To Compensation 119

What is compensation and why is it needed?	119
The initial setting for compensation	120
When is trial machining required?	120
What happens as tools begin to wear?	121
What do you shoot for?	121
Why do programmers have to know this?	121
Understanding offsets	121
Offset organization	122
Offset pages on the display screen	122
Key points for Lesson Eight:	124

Lesson 9: Geometry Offsets And Wear Offsets 125

Review of reasons for using geometry offsets to assign program zero	125
How geometry offsets work	125
The total program zero assignment value	126
Warning about the machine lock feature:	127
Minimizing program zero assignment effort from job to job	127
So when do you clear geometry offsets?	129
Wear offsets	129
Which dimension do you choose for sizing?	130
How wear offsets are programmed	130
What about wear offset cancellation?	131
Secondary wear offset applications	131
Flip jobs	132

Two or more critical diameters 132	How to use our given formats 161
Unwanted taper 132	Key points for Lesson Eleven: 162
Grooving into different areas of the workpiece 132	
Key points for Lesson Nine: 132	
Lesson 10: Tool Nose Radius Compensation 137	Lesson 12: Four Types Of Program Format 163
Keeping the cutting edge flush with the work surface at all times 139	Format for assigning program zero with geometry offsets 164
When to use tool nose radius compensation 140	Format for assigning program zero in the program with G50 165
Steps to programming tool nose radius compensation 140	A reminder about the program's starting point and tool change position 165
Instating tool nose radius compensation 140	Program startup format (assigning program zero in the program) 165
Programming motion commands to machine the workpiece 141	Tool ending format (assigning program zero in the program) 166
Canceling tool nose radius compensation 142	Tool startup format (assigning program zero in the program) 167
An example program 142	Program ending format (assigning program zero in the program) 167
Tool nose radius compensation from a setup person's point of view 143	Understanding the formats 167
What if my machine does not have geometry offsets? 145	G Words 167
What if I forget to enter tool nose radius compensation values? 145	M Words 168
What if I enter tool nose radius compensation values into wear offsets? 145	Other M Words Related to Turning Centers 168
What if I enter tool nose radius compensation values into both the geometry and wear offsets? 145	Other Words In The Format 169
Programming tool nose radius compensation value entries 145	Example programs showing format for turning centers 169
Another example program showing tool nose radius compensation 145	Where are the restart commands? 171
Key points for Lesson Ten: 147	Example program when assigning program zero in the program 171
	Where are the restart commands? 172
Key Concept 5: You Must Provide Structure To Your CNC Programs 149	Suggestions for cycle time improvements. 173
Lesson 11: Introduction To Program Structure 151	Combine M codes in motion commands 173
Objectives of your program structure 151	Minimize spindle dead time 173
Reasons for structuring programs with a strict and consistent format 151	Efficiently programming spindle range changes 176
Familiarization 151	Minimize spindle reversals 177
Consistency 152	Key points for Lesson Twelve: 178
Re-running tools in the program 152	
Efficiency limitations 154	Key Concept 6: Special Features That Help With Programming 181
Machine variations that affect program structure 155	Control series differences 182
M code differences 155	Lesson 13: One-Pass Canned Cycles 183
G code numbering differences 156	Cycle consistencies 183
Turret variations 157	G90 - One pass turning and boring cycle 184
How do you determine a safe yet efficient index position? 157	G92 - One pass threading cycle 185
What if my machine doesn't have geometry offsets? 158	G94 - One pass facing command 186
A few spindle concerns 159	Example of G90 and G94 186
Spindle limiting 159	Example of G92 command 187
Choosing the appropriate spindle range 160	Key points for Lesson Thirteen: 188
Which direction do you run the spindle? 160	Lesson 14: G71 And G70 – Rough Turning And Boring Followed By Finishing 189
How do you check what each tool has done? 160	G71 - Rough turning and boring 189
Safety commands 160	The two phases of G71 190
	Understanding G71 command words 192
	P word 192
	Q word 192
	U word 192
	W word 192
	D word 192
	F word 193

What about finishing? 193
 Example showing G71 for rough turning and G70 for finish turning 193
 Using G71 for rough boring 195
 Limitations of the G71 command 197
 Different format for some controls (with two-line multiple repetitive cycle) 198
 Key points for Lesson Fourteen: 198

Lesson 15: G72-G75 – Other Multiple Repetitive Cycles 201

G72 - Rough facing 201
 Different format for two-command multiple repetitive cycles 203
 G73 - pattern repeating 203
 D word 204
 I word 204
 K word 204
 Example of G73 pattern repeating 205
 Can you use G73 for castings and forgings? 206
 Different format for two-command multiple repetitive cycles 207
 G74 - peck drilling 207
 What if I must clear chips between pecks? 208
 Different format for two-command multiple repetitive cycles 209
 G75 - grooving cycle 209
 Key points for Lesson Fifteen: 210

Lesson 16: G76 Threading Command 211

X word 211
 Z word 212
 What is thread chamfering? 212
 K word 212
 D word 212
 A word 213
 F word and E word 213
 I word 213
 Q word 214
 Example program for threading 214
 Other tips on threading 215
 When possible, thread in the lowest spindle range 215
 Thread in the rpm mode (G97) 215
 Watch out for maximum allowable feedrate 215
 Thread with thread chamfering turned off 215
 Finish the thread before removing workpiece 216
 Right hand threads versus left hand threads 216
 Offsetting for threading tools 216
 Start the tool far enough away from the thread being machined 216
 Minimum depth-of-cut, final pass depth, and number of spring passes 216
 Disabled or modified control functions during threading 216
 Tapered threads 217
 Multiple start threads 218
 Different format for two-command multiple repetitive cycles 220

What about tapping? 220
 Tap in the rpm mode 220
 Tap in the low range 220
 Use G32 as the motion command for tapping 221
 Use a tension/compression tap holder 221
 Keep the approach position 0.2 inch from the Z surface to tap 221
 Key points for Lesson Sixteen: 222

Lesson 17: G76 Working With Subprograms 223

The difference between main- and sub- programs 223
 Loading multiple programs 223
 Words used with subprograms 224
 A quick example 224
 Nesting subprograms 226
 Applications for subprograms 226
 Repeated machining operations 226
 Control programs 226
 Utility applications 227
 Example for repeating machining operations - multiple identical grooves 227
 Example for control program applications - flip jobs 229
 Example for utility applications - bar feeder activation 230
 Special notes about M99 232
 Ending a main program with M99 232
 Changing the order of program execution with M99 232
 What is parametric programming (custom macro B)? 235
 Part families 235
 User defined canned cycles 236
 Utilities 236
 Complex motions and shapes 237
 Key points for Lesson Seventeen: 238

Lesson 18: Other Special Programming Features 239

Block delete (also called optional block skip) 239
 Applications for block delete 240
 Another optional stop 240
 Trial machining 240
 Warning about block delete applications 242
 Sequence number (N word) techniques) 242
 Eliminating sequence numbers 242
 Using special sequence numbers in program restart commands 242
 Documenting your programs with messages in parentheses 244
 General information about the job 244
 Tool information 245
 At every program stop 245
 To document anything out of the ordinary 245
 For changes made after a dispute 246
 Automatic corner rounding and chamfering 246
 Other G codes of interest 248
 G04 - Dwell command 248

Other G codes 249	Rotating tools 267
Key points for Lesson Eighteen: 250	Special tool holders 267
Lesson 19: Special Machine Types And Accessories 251	Precise control of main spindle rotation 268
Work holding and work support devices 251	Only one way to specify speed and feedrate 268
Work holding devices 251	Hole machining canned cycles 268
Three jaw chucks 252	Polar coordinate interpolation 268
Programmable features of three jaw chucks 254	Selecting the main spindle mode 269
Collet chucks 255	Programming an indexer 269
Work support devices 257	Example program for an indexer 270
Tailstocks 257	Programming a rotary axis (C axis) 272
The tailstock body 257	Angular values 272
Tailstock quill 258	Zero return position 272
Tailstock center 258	Rapid versus straight line motion 272
Tailstock alignment problems 258	Program zero assignment 272
Programming considerations 258	Absolute versus incremental 273
Steady rests 259	Canned cycles for hole machining 274
Bar feeders 260	How do you specify the machining direction? 274
How a bar feeder works 260	Canned cycle types 274
Workholding considerations 260	Words used in canned cycles 275
Styles of bar feeders 260	Understanding polar coordinate interpolation 276
How to program for bar feeders 261	Other machine types 280
Determining how much to feed the bar 261	Twin spindle turning centers 281
The steps to bar feeding 262	Sub-spindle turning centers 281
The redundancy of bar feed programming 264	Swiss-type turning centers (also called sliding headstock turning centers) 281
When to program the bar feed 264	Practice exercises 283
Ending a bar feed program 264	Programming Activities 319
An example bar feeding program 265	Answers to Exercises 367
Part catchers 267	Answers to programming activities 376
Live tooling 267	
Features of live tooling turning centers (also called mill/turn machines) 267	

