

PREFACE..... 9

- THE WOW-FACTOR..... 9
- POSSIBILITIES 9
 - Why so many?*..... 10
- ENTER YOUTUBE 10
- HOBBYIST VERSUS INDUSTRIAL USE 11
- OUR FOCUS 11
- HOBBYIST-GRADE PRINTER RECOMMENDATIONS 12
- BIGGER ISN'T NECESSARILY BETTER 12
- WHAT TO PRINT 12
- SUPPLIERS OF MATERIALS SHOWN IN THIS SECTION 13

LESSON 1: KNOW THE TECHNOLOGIES SURROUNDING YOUR 3D PRINTER 15

- THE 3D PRINTING PROCESS..... 15
 - The idea* 15
 - The model* 16
 - Export the .STL file* 16
 - Import the .STL file to the Slicing software and adjust/confirm settings*..... 17
 - Transfer the G-code program to the 3D printer*..... 18
 - Get the 3D printer ready and activate the G-code program*..... 18
- HOW SLICING SOFTWARE WORKS 18
- LAYING DOWN THE LAYERS..... 19
 - Layering by extrusion 20
- OTHER 3D PRINTING TECHNOLOGIES 21
 - Hybrid 3D printers*..... 22
 - A really big extruder*..... 22
 - Layering with lasers* 22
- APPLICATIONS FOR 3D PRINTERS..... 22
 - Industry*..... 23
 - Hobbyist/personal*..... 24

LESSON 2: KNOW YOUR 3D PRINTER..... 25

- 3D PRINTER TYPES 25
 - Cartesian-type 3D printers*..... 25
 - Delta-type 3D printers*..... 26
- FUNCTIONS AND COMPONENTS 27
 - Home position*..... 27
 - Filament spool holder* 28
- ELECTRONIC COMPONENTS 29
 - Power supply*..... 29
 - Axis limit switches*..... 29
 - Printed circuit board/s* 29
 - Fans*..... 29
 - Display screen* 29
 - Extruder and nozzle assembly*..... 29
 - How hot? 31
 - Nozzle priming..... 31
 - Model cooling fan (also called the part cooling fan)* 33
 - Multiple nozzles/extruders*..... 33
 - Beds and build plates*..... 34
 - The need for heat 34
 - How hot? 35
 - Build plate surfaces 35
 - A few suggestions 35
 - Enclosures* 38
 - Operator's control panel*..... 38

Information display	39
Preparation (the “Prepare” menu).....	39
Function controls (the “Control” menu)	39
Print activation.....	40
SUPPLIERS OF MATERIALS SHOWN IN THIS LESSON	40
LESSON 3: KNOW YOUR PRINTING MATERIAL.....	41
PLA (STANDS FOR POLYLACTIC ACID)	41
WOOD	42
ABS (STANDS FOR ACRYLONITRILE BUTADIENE STYRENE):	42
PTEG (POLYETHYLENE TEREPHTHALATE)	43
PVA (POLYVINYL ALCOHOL).....	44
NYLON	44
FLEXIBLE FILAMENTS (LIKE TPU - THERMOPLASTIC POLYURETHANE)	44
OTHERS.....	45
FILAMENT VARIATIONS AND CONCERNS THAT AFFECT 3D PRINTING	45
<i>Filament properties</i>	45
<i>Filament size</i>	45
<i>Moisture content</i>	45
<i>Handling the filament spool</i>	45
LESSON 4: KNOW HOW YOUR 3D PRINTER IS CALIBRATED	47
WHY CALIBRATE?	47
WHAT KIND OF PRECISION CAN YOU EXPECT?	47
ACCURACY VERSUS REPEATABILITY	48
BEFORE YOU START CALIBRATING.....	48
CALIBRATION FOR CARTESIAN-TYPE 3D PRINTERS.....	48
<i>Axis squareness</i>	48
How to calibrate.....	50
<i>Build plate flatness</i>	50
<i>Bed flatness</i>	51
<i>Nozzle height and build plate/bed level</i>	51
Mechanical adjustment.....	52
Techniques for build plate leveling	52
Build plate leveling G-code program:.....	57
Build plate/bed automatic leveling probes	58
<i>Software calibrations</i>	59
Related G-code commands	59
<i>Extruder filament flow</i>	60
The possibilities.....	60
Factors that affect extrusion calibration	60
How to calibrate.....	61
To calculate the new value:	62
Making the adjustment.....	62
Another way to calibrate the extruder.....	63
Multiple material settings	63
Setting the retraction amount	63
<i>Axis travel-distance calibration</i>	64
Calibrating X and Y	64
Calibration for the Z axis steps-per-unit value	66
Variations that affect axis-related steps-per-unit calibrations.....	67
<i>Calibrating for acceleration and jerk</i>	67
Initial settings.....	68
CALIBRATION FOR DELTA-TYPE 3D PRINTERS	69
<i>Model size and concave versus convex</i>	69
<i>Z axis position/height</i>	71
<i>Using an auto-leveling probe</i>	72
Z position.....	73

<i>Build plate level</i>	73
<i>Axis squareness</i>	73
<i>Build plate flatness</i>	73
<i>Bed flatness</i>	74
<i>Build plate/bed level</i>	74
<i>Software calibrations</i>	74
Related G-code commands	74
<i>Extruder calibration</i>	75
The possibilities	75
Factors that affect extrusion calibration	75
How to calibrate	76
To calculate the new value:.....	77
Making the adjustment	77
Another way to calibrate the extruder	78
Multiple material settings.	78
Setting the retraction amount.....	78
<i>Axis travel-distance calibration</i>	79
<i>Calibrating for acceleration and jerk</i>	79
Initial settings	80
DETERMINING THE RIGHT NOZZLE TEMPERATURE	81
MEASURING THE CAPABILITIES OF YOUR 3D PRINTER	82
<i>Limitation of Thingiverse.com designs</i>	83
<i>3D printer capability tests</i>	83
Clearance test.....	83
Cheating with scale and flow control	84
Creating your own test models	84
Testing to determine slicer settings	84
LESSON 5: GET READY TO PRINT A MODEL	87
SLICER SETTINGS	87
<i>Our slicer choice</i>	87
<i>Initial setup</i>	88
<i>Standard printing profiles</i>	90
<i>Process to slice a model</i>	91
<i>The most important printing profile settings</i>	94
MANIPULATING THE MODEL ON THE BUILD PLATE	98
<i>Position on the build plate</i>	98
<i>Scale the model (change its size)</i>	98
<i>Rotate the model</i>	99
<i>Mirror the model (make left and right-hand versions)</i>	99
DOWNLOADING MODELS FROM THINGIVERSE.COM	100
MODEL DESIGN ATTRIBUTES THAT AFFECT 3D PRINTING	102
<i>Support for overhangs</i>	105
Internal support.....	106
External support	107
CHOOSING THE BEST ORIENTATION ON THE 3D PRINTER’S BUILD PLATE.....	108
TAKING FULL ADVANTAGE OF YOUR PRINT VOLUME.....	110
ENSURING BUILD PLATE ADHESION	111
<i>Dealing with build plate surface-flatness variations</i>	111
<i>Model size versus adhesion</i>	112
<i>Material variations</i>	112
<i>Enter your slicing software</i>	113
Brims.....	113
Rafts.....	113
LESSON 6: KNOW HOW TO PRINT MODELS AND PERFORM RELATED TASKS	115
TOOLS, ACCESSORIES, AND SOFTWARE	115

<i>Essentials</i>	115
Essential tools	115
Essential accessories	116
Essential software	117
IMPORTANT AND HELPFUL ITEMS	117
<i>Important tools</i>	117
<i>Helpful accessories</i>	118
<i>Helpful software</i>	118
3D PRINTING TASKS	118
<i>Turn your 3D printer on (and off)</i>	118
<i>Load/change filament</i>	118
<i>Attach the build plate</i>	120
<i>Clean/prepare the build plate</i>	120
<i>Set/check the build plate level and nozzle height</i>	120
<i>Transfer the G-code program to the 3D printer</i>	120
<i>Activate the G-code program to start a print</i>	120
<i>Be sure the nozzle is clean when it begins depositing the first layer</i>	121
<i>Monitor – monitor – monitor</i>	121
Be ready for failed prints.....	121
<i>Remove the build plate</i>	122
<i>Wait until the model cools before you remove it</i>	122
<i>Remove the completed model from the build plate</i>	122
<i>Examine/inspect the completed model</i>	122
How good is good enough?.....	122
TROUBLESHOOTING 3D PRINTING ISSUES	123
<i>So, what else can go wrong during a print?</i>	124
Slicer settings that can cause bad printing.....	124
3D printer issues/malfunctions	125
<i>A few maintenance tasks</i>	126
Cleaning	126
Lubrication	126
Components most prone to failure that will eventually have to be replaced.....	126
PRINTING A FEW MODELS.....	126
<i>The thing about Thingiverse</i>	127
<i>Notes about these exercises</i>	127
<i>Project #1: The 3D printing world’s most popular benchy</i>	127
Download the .STL files and slice the model.....	128
Print the model	129
Do you see evidence of stringing?	130
Speed kills (quality).....	130
Save the slicer settings as a custom printing profile.....	132
Reduce Layer Height to get smoother surfaces	133
<i>A warning about saving settings</i>	134
Create a new custom printing profile that includes the 0.1-mm layer height change.....	134
<i>Project #2: Something a bit more useful – Hex-shaped modular drawers</i>	134
A problem	135
<i>Project #3: Jewelry box</i>	136
<i>Project #4: Battery cases</i>	137
<i>Project #5: Helical bearing assembly</i>	138
<i>Project #6: Platform jack and more one-print assemblies</i>	139
LESSON 7: UNDERSTAND G-CODE – COMMANDS THAT DRIVE YOUR 3D PRINTER	141
G-CODE COMMANDS THAT START A PROGRAM	141
CONTROLLING AXIS MOTION	142
<i>G28 – home command</i>	143
<i>G21 – metric mode</i>	143
<i>G90 – Absolute positioning mode</i>	143
<i>G0 – traveling</i>	143

<i>G1 – linear interpolation (straight movement)</i>	144
EXTRUDER CONTROL.....	145
BED AND NOZZLE TEMPERATURE CHANGES.....	145
<i>M190 S60</i>	145
<i>M104 S205</i>	145
<i>M109 S205</i>	145
PART-COOLING-FAN CONTROL.....	146
<i>M107 – Part cooling fan off</i>	146
<i>M106 – Part cooling fan on</i>	146
M117 – PLACE A MESSAGE ON THE DISPLAY SCREEN.....	146
FIRMWARE SETTING COMMANDS.....	146
DETERMINING THE MEANING OF OTHER G-CODE COMMANDS.....	146
UTILITY PROGRAMS.....	146
<i>Build plate leveling</i>	146
New M-codes in the calibration-assist program.....	147
Modify this program to create your own build plate leveling program.....	147
LESSON 8: KNOW HOW TO DESIGN MODELS FOR 3D PRINTING.....	149
GET READY TO DESIGN.....	149
<i>3D modeling software default resolution issue</i>	149
DESIGN WITH YOUR 3D PRINTER’S CHARACTERISTICS IN MIND.....	150
<i>Dealing with support issues</i>	150
Your first choice: Eliminate/minimize the need for support	150
2 nd alternative: Plan support for less critical model attributes	153
3 rd alternative: Design your own support	153
4 th alternative: Make it easy to remove support	154
APPLY THE RIGHT AMOUNT OF CLEARANCE BETWEEN MATING COMPONENTS.....	154
<i>Test your intended clearance amount</i>	154
<i>Consider 3D printing issues</i>	155
<i>Consider the length of engagement</i>	156
<i>Other fits</i>	156
<i>Integral printing</i>	156
Chamfer bottom surfaces.....	157
DESIGN WITH YOUR 3D PRINTER’S DIMENSIONAL ACCURACY IN MIND.....	157
DESIGN WITH EASE OF 3D PRINTING IN MIND.....	158
<i>Orientation</i>	158
<i>Scaling</i>	159
<i>Adhesion and removal from build plate</i>	159
Design to make models stick without warpage.....	159
Designing with easy removal from the bed plate in mind.....	160
DESIGN WITH NOZZLE SIZE IN MIND.....	160
DESIGN WITH MODEL COOLING IN MIND.....	161
DESIGN WITH LAYERING DIRECTION IN MIND.....	161
RELATE WHAT YOU KNOW.....	162
LESSON 9: LEARN DESIGN SOFTWARE – AND OTHER SOFTWARE FOR 3D PRINTING.....	165
THE 3D MODELING SOFTWARE CHOICE.....	165
<i>Purpose</i>	165
<i>Ease-of-use and learning curve</i>	165
<i>Cost</i>	165
<i>Output</i>	165
<i>Design software used for demonstration</i>	165
GETTING STARTED WITH 3D MODELING SOFTWARE.....	166
<i>Extrusion: getting from 2-D to 3-D</i>	166
<i>Specifying precise dimensions and relationships</i>	168
Draw a 20-mm calibration cube.....	168
<i>Using guidelines to specify relationships</i>	170

OTHER SOFTWARE RELATED TO 3D PRINTING174
 .STL file editors174
 Firmware editors and uploaders175
 3D printer host software175
 Wireless printing systems.....176